


# Operating Instructions

## Moisture Analyzer

### Excellence Plus HX204



METTLER TOLEDO



# Table of Contents

<b>1</b>	<b>Introduction</b>	<b>7</b>
1.1	Conventions and Symbols Used in these Operating Instructions	7
<b>2</b>	<b>Safety Information</b>	<b>8</b>
2.1	Definition of Signal Warnings and Symbols	8
2.2	Product Specific Safety Notes	8
<b>3</b>	<b>Design and Function</b>	<b>11</b>
3.1	Overview	11
3.1.1	Drying Unit	11
3.1.2	Terminal	12
3.1.3	Keys on the Terminal	14
3.2	User Interface	15
3.2.1	User "Home" Screen	16
3.2.2	Basic Elements on Touch Screen	17
3.2.3	Icon and Buttons	17
3.2.3.1	Status Message Icons	17
3.2.3.2	Title Bar Icons	17
3.2.3.3	Action Bar Buttons	17
3.2.4	Input Dialogs	18
3.2.4.1	Entering Text and Numbers	18
3.2.4.2	Entering Numerical Values	19
3.2.4.3	Changing Date and Time	20
3.2.5	Lists and Tables	21
3.2.6	Work Screen	22
3.2.7	Graphics View	23
<b>4</b>	<b>Installation and Putting into Operation</b>	<b>24</b>
4.1	Scope of Delivery	24
4.2	Location	24
4.3	Opening and Closing Sample Chamber	25
4.4	Connecting Instrument	25
4.5	Setting up Drying Unit	26
4.6	Leveling Drying Unit	27
4.7	Anti-theft Device	28
4.8	Setting Reading Angle of Terminal	28
4.9	Setting Date and Time	28
4.10	Adjustment	29
<b>5</b>	<b>My First Measurement</b>	<b>30</b>
<b>6</b>	<b>Settings</b>	<b>33</b>
6.1	User Preferences	34
6.1.1	Languages	34
6.1.2	Screen	34
6.1.3	Sound	34
6.1.4	Password	35
6.2	System Settings	36
6.2.1	Regional Settings	36

6.2.2	Peripherals	36
6.2.3	Default Settings	37
6.2.3.1	Default Languages	38
6.2.3.2	Default Screen Settings	38
6.2.4	Touch Screen Adjustment	38
6.3	Applications Settings	40
6.3.1	Identifications Management	40
6.3.2	Print and Output Management	40
6.4	Quality Management	42
6.4.1	Test / Adjustment settings	42
6.4.1.1	Equipment	42
6.4.1.2	Test Settings	43
6.4.1.3	Adjustment Settings	44
6.4.1.4	Print and Output Settings	44
6.4.1.5	FACT (Fully automatic adjustment)	45
6.5	User Management	46
6.5.1	Groups	46
6.5.2	Users	48
6.5.3	Account Policies	49
6.6	System- and Data Management	50
6.6.1	Export / Import	50
6.6.2	Back up / Restore	51
6.6.3	Reset	52
6.6.4	Update	52
<b>7</b>	<b>Test/Adjust</b>	<b>55</b>
7.1	Adjustments	55
7.1.1	Weight Adjustment - Internal	56
7.1.2	Weight Adjustment - External	56
7.1.3	Temperature Adjustment	57
7.1.4	Adjustment Printout Examples	59
7.2	Tests	60
7.2.1	Weight test - internal	60
7.2.2	Weight test - external	60
7.2.3	Temperature test	61
7.2.4	Test Printout Examples	62
7.3	History	63
<b>8</b>	<b>Method Definition</b>	<b>64</b>
8.1	Main Measuring Parameters	66
8.1.1	Settings of Drying Program	66
8.1.1.1	Settings of Standard drying	66
8.1.1.2	Settings of Rapid drying	67
8.1.1.3	Settings of Gentle drying	68
8.1.1.4	Settings of Step drying	69
8.1.1.5	Settings of Switch-off Criterion (SOC)	70
8.1.2	Settings of Display Mode	72
8.1.3	Settings of Start Weight	74
8.2	Result and Values Handling	75
8.2.1	Control limits	75

8.2.2	Resolution	76
8.3	Workflow Handling	77
8.3.1	Starting Mode	77
8.3.2	Preheating	77
8.4	General Method Properties	79
8.4.1	Method name	79
8.5	Test a Method	80
<b>9</b>	<b>Measurement</b>	<b>81</b>
9.1	Performing a Measurement	81
9.2	Work with Weighing-in Aid	83
9.3	Using Shortcuts	83
<b>10</b>	<b>Results</b>	<b>85</b>
10.1	Graphical Evaluations of Measurement Results	85
10.2	Information on Printouts	87
10.3	Exporting Results	88
<b>11</b>	<b>Maintenance</b>	<b>90</b>
11.1	Cleaning	90
11.1.1	Sample Chamber	91
11.1.2	Heating Module	91
11.1.3	Fan Grill	93
11.2	Dust Filter	93
11.3	Replacing Power Line Fuse	94
11.4	Disposal	94
<b>12</b>	<b>Troubleshooting</b>	<b>95</b>
12.1	Error Messages	95
12.2	Status Messages	95
12.3	What to Do if...	97
<b>13</b>	<b>Technical Data</b>	<b>99</b>
13.1	General Technical Data	99
13.1.1	Explanatory note to periodic inspections in accordance with EU Directive 2001/95/EC	101
13.2	Dimensions	102
13.3	Interfaces Specification	103
13.3.1	RS232C	103
13.3.2	USB Host	104
13.3.3	USB Device	104
<b>14</b>	<b>Accessories and Spare Parts</b>	<b>105</b>
<b>15</b>	<b>Appendix</b>	<b>109</b>
15.1	How to Obtain Best Results	109
15.1.1	Measurement Principle of Halogen Moisture Analyzer	109
15.1.2	Notes on Adjustment of Balance and Heating Module	109
15.1.3	Optimum Sample Preparation	110
15.1.4	Further Information on Moisture Determination	110

15.2	Recommended Printer Settings	110
15.3	Installing USB Device Driver	111
15.4	Third Party License/Notice	112
<b>16</b>	<b>Index</b>	<b>114</b>

---

# 1 Introduction

Thank you for purchasing a Halogen Moisture Analyzer from METTLER TOLEDO.

Your Moisture Analyzer is fast and reliable. It offers a high level of operating convenience and useful functions to facilitate determination of the moisture content of your samples.

Behind your instrument stands METTLER TOLEDO, a leading manufacturer of not only balances and scales for the lab and production, but also analytical measuring instruments. A customer service network covering the entire globe with well trained personnel is your service at all times, whether you are choosing accessories or require guidance for a specific application to ensure optimum utilization of your instrument.

Your Halogen Moisture Analyzer is used for determining the moisture content of almost any substance. The instrument works on the thermogravimetric principle. At the start of the measurement the Moisture Analyzer determines the weight of the sample, the sample is then quickly heated by the integral halogen heating module and the moisture vaporizes. During the drying process the instrument continually measures the weight of the sample and displays the reduction in moisture. Once drying has been completed, the moisture or solids content of your sample is displayed as the final result.

Of decisive importance in practice is the rate of heating and even heating of the surface of the sample. In comparison with conventional infrared heating or the drying oven method, for example, the halogen heating module of your instrument needs a shorter time to reach its maximum heating power. It also allows use of high temperatures, an additional factor in shortening the drying time. Uniform heating of the sample material ensures good repeatability of the drying results and makes it possible to use a smaller amount of sample.

The Moisture Analyzer conforms with all common standards and directives. It supports stipulations, work techniques and result records as demanded by all international quality assurance systems, e.g. GLP (Good Laboratory Practice), GMP (Good Manufacturing Practice). The instrument has a CE declaration of conformity and METTLER TOLEDO as the manufacturer has been awarded ISO 9001 and ISO 14001 certification. This provides you with the assurance that your capital investment is protected in the long term by a high product quality and a comprehensive service package (repairs, maintenance, servicing, adjustment service).

## Finding More Information

► [www.mt.com/hxhs](http://www.mt.com/hxhs)

### Software version

These operating instructions are based on the initially installed firmware (software) version V1.20.

## 1.1 Conventions and Symbols Used in these Operating Instructions

Key and button designations are indicated by a picture or text in square brackets (e.g. [Save])

These symbols indicate an instruction:

- prerequisites
- 1 steps
- 2 ...
- ⇒ results

## 2 Safety Information


### 2.1 Definition of Signal Warnings and Symbols

Safety notes are marked with signal words and warning symbols. These show safety issues and warnings. Ignoring the safety notes may lead to personal injury, damage to the instrument, malfunctions and false results.

#### Signal Words

<b>WARNING</b>	for a hazardous situation with medium risk, possibly resulting in severe injuries or death if not avoided.
<b>CAUTION</b>	for a hazardous situation with low risk, resulting in damage to the device or the property or in loss of data, or minor or medium injuries if not avoided.
<b>Attention</b>	(no symbol) for important information about the product.
<b>Note</b>	(no symbol) for useful information about the product.

#### Warning Symbols



### 2.2 Product Specific Safety Notes

#### General Safety Information

Your instrument meets the state of the art technology and complies with all recognized safety rules, however, certain hazards may arise in extraneous circumstances. Do not open the housing of the instrument: It does not contain any parts which can be maintained, repaired or replaced by the user. If you ever have problems with your instrument, contact your authorized METTLER TOLEDO dealer or service representative.

Always operate and use your instrument only in accordance with the instructions contained in this manual. The instructions for setting up your new instrument must be strictly observed.

**If the instrument is not used according to these Operating Instructions, protection of the instrument may be impaired and METTLER TOLEDO assumes no liability.**

#### Intended Use

Your Moisture Analyzer is used for determining the moisture in samples. Use the instrument exclusively for this purposes. Any other type of use and operation beyond the limits of technical specifications without written consent from Mettler-Toledo AG, is considered as not intended.

Moisture determination applications must be optimized and validated by the user according to local regulations. Application-specific data provided by METTLER TOLEDO is intended for guidance only.



It is not permitted to use the instrument in explosive atmosphere of gases, steam, fog, dust and flammable dust (hazardous environments).

## **Staff Safety**

The moisture Analyzer may be operated only by trained personnel who are familiar with the properties of the samples used and with the handling of the instrument.

In order to use the instrument, you must have read and understood the operating instructions. Keep the operating instructions for further reference.

Never make any modifications or constructional alterations to the instrument and use only original spare parts and optional equipment from METTLER TOLEDO.

## **Protective Clothing**

It is advisable to wear protective clothing in the laboratory when working with the instrument.



A lab coat should be worn.



A suitable eye protection such as goggles should be worn.



Use appropriate gloves when handling chemicals or hazardous substances, checking their integrity before use.

## **Safety Notes**

---

### **WARNING**



#### **Risk of electric shock**

Your instrument is supplied with a 3-pin power cable with an equipment grounding conductor. Only extension cables which meet this relevant standards and also have an equipment grounding conductor may be used. Intentional disconnection of the equipment grounding conductor is prohibited.

---

### **CAUTION**



#### **The Halogen Moisture Analyzer works with heat!**

- a) Ensure sufficient free space around the instrument to avoid heat accumulation and overheating (approx. 1 m free space above the heating module).
  - b) The vent over the sample must never be covered, plugged, taped over or tampered with in any other way.
  - c) Do not place any combustible materials on, under or next to the instrument since the area around the heating module may be hot.
  - d) Exercise caution when removing the sample. The sample itself, the sample chamber, the draft shield and any sample vessels used may still be very hot.
  - e) During operation, you should never open the heating module itself as the ring-shaped heating reflector or its protective glass can reach 400 °C! If you have to open the heating module e.g. for maintenance, disconnect the instrument from the power supply and wait until the heating module has cooled down completely.
  - f) No modifications must be made within the heating module. It is particularly dangerous to bend any components or remove them or to make any other changes.
-

## Certain samples require special care!

With certain types of samples, there is a possibility of danger to personnel or damage of property. Please note that the user always has the responsibility and liability for damage caused by use of any types of samples!

---

### CAUTION



#### Fire or Explosion

- Flammable or explosive substances.
  - Substances containing solvents.
  - Substances which evolve flammable or explosive gases or vapors when heated.
- a) In cases of doubt, perform a careful risk analysis.
  - b) Work at a drying temperature that is low enough to prevent the formation of flames or an explosion.
  - c) Wear protective goggles.
  - d) Work with small amounts of sample.
  - e) **Never leave the instrument unattended!**
- 

### WARNING



#### Substances which contain toxic or caustic components

Toxic gases produced during drying could cause irritations (eyes, Skin, breathing), illness or death.

- Such substances may be dried only in a fume cupboard.
- 

### CAUTION



#### Corrosion

Substances which evolve corrosive vapors when heated (e.g. acids).

- Work with small amounts of samples as the vapor can condense on cooler housing parts and cause corrosion.
-


### 3 Design and Function

In order to work with your Moisture Analyzer, you need to familiarize yourself with the instrument layout, drying unit, graphical user interface of the touch screen as well as the terminal.

#### 3.1 Overview

##### 3.1.1 Drying Unit

Description of the components and the external connectors on the back of the drying unit (Weighing unit with heating module).



##### Connectivity




<b>System connection</b>	Interface for the communication between terminal and drying unit.
<b>Power supply socket</b>	Power supply inlet socket for the country-specific power cable. The socket has a built in fuse compartment containing a replacement fuse.

### 3.1.2 Terminal

Description of the connections at the terminal (Input and output unit with interfaces).




- 1** WVGA color display (touch screen)
- 2** Foot
- 3** USB Host connection
- 4** Faceplate
- 5** USB Host connection
- 6** USB Device connection
- 7** RS232C connection
- 8** Ethernet RJ45 connection (n.a.)
- 9** System connection (terminal cable)
- 10** Memory Card slot for SD Card



## Connectivity

<b>System connection</b>	Interface for the communication between terminal and drying unit.
<b>RS232C connection</b>	RS232C interface for connecting the instrument to a peripheral device (e.g. printer or a PC with a 9-pin male connector).
<b>USB Host connection</b>	USB interface for connecting a peripheral device to the instrument (e.g. memory stick up to 32 GB). Type A Socket.
<b>USB Device connection</b>	USB interface for connecting the instrument to a peripheral device with an USB host connection (e.g. PC). Type-B socket.
<b>Memory Card slot</b>	The memory card slot fits Secure Digital Memory Cards. SD and SDHC types as well as sizes up to 32 GB are supported. You can use it as an external storage device e.g. to store measured results.  <b>Note</b> SDXC types are not supported.

### 3.1.3 Keys on the Terminal



EXCELLENCE Plus

		Name	Explanation
1		ON/OFF	To switch on or off (standby operation) the instrument. <b>Note</b> Do not disconnect the instrument from the power supply except if you will not be using the instrument for an extended period.
2		Home	To return from any menu level, or other window to the user home screen.
3		Open/Close	To open or close the sample chamber motorized. <b>Attention</b> Do not open the sample chamber manually. Only open manually in emergency situations. In all other cases use always the [↔] key. <b>See</b> Opening and Closing Sample Chamber (page 25)
4		Touch screen	

## 3.2 User Interface

The colored touch screen is a touch-sensitive WVGA monitor. The touch screen not only displays information, it also allows you to enter commands by touching certain areas on its surface: You can choose the information displayed on the screen, change terminal settings or perform certain operations on the instrument.

Only those elements which are available for the current dialog appear on the display.

### Buttons on the Touch Screen

Buttons are software elements on the touch screen (Soft keys).

---

#### CAUTION




**Do not touch the touch screen with pointed or sharp objects!**

This may damage the touch screen.

---

### 3.2.1 User "Home" Screen

The user **Home** screen is the main screen and appears after startup or login of the instrument. All screens of the user interface can be accessed from the home screen. Returning to the **Home** screen is possible from all other screens of the user interface by pressing the [**Home**] key or tapping the [**Home**] button.




	Name	Explanation
1	<b>Measurement</b>	<b>Start measurement</b> Prerequisite: Method is defined and all necessary settings are made. For further information <b>see</b> My First Measurement (page 30) and Measurement (page 81).
	<b>Results</b>	<b>Show results</b> Under this menu item, all measurement results can be displayed, printed or exported. For further information <b>see</b> Results (page 85).
	<b>Method Definition</b>	<b>Define, edit or delete a method</b> All actions using in a drying method, can be defined under this menu item. Description of the menu item <b>see</b> Method Definition (page 64).
	<b>Test/Adjust</b>	<b>Adjust or test the instrument</b> Under this menu item, the integrated balance and the heating module can be adjusted or tested. Description of the menu item <b>see</b> Test/Adjust (page 55).
	<b>Settings</b>	<b>Define general settings</b> All settings of the system can be defined, e.g. system settings, user management or user preferences. These settings are usually made during installation of the instrument. Description of the menu item <b>see</b> Settings (page 33)
2		<b>User shortcuts</b> User-specific shortcuts for frequently used methods. Shortcuts are saved in the user profile. How to create shortcuts <b>see</b> Using Shortcuts (page 83).
3	<b>Instrument info</b>	Shows general info about the instrument like type, serial number, software version.

## 3.2.2 Basic Elements on Touch Screen

The graphical user interface consists of the following basic elements.

### Screen Areas and their Elements



	Name	Explanation
<b>1</b>	Status Bar	The status bar contains the user name, status icons as well as date and time. <b>See</b> Status Message Icons (page 17).
<b>2</b>	Title Bar	The title bar contains elements for the user's orientation and information, as well as for special functions. <b>See</b> Title Bar Icons (page 17).
<b>3</b>	Content Area	The content area is the main working area of the menus and the applications, content depends on application or performed action. The content area also shows graphic illustrations such as the curve diagram of a data set (e.g. drying curve).
<b>4</b>	Action Bar	The action bar contains action buttons for triggering the actions which are required and available in the current dialog (e.g. <b>Back</b> , <b>-&gt;O/T&lt;-</b> , <b>Print</b> , <b>Save</b> , <b>Delete</b> , <b>OK</b> ). <b>See</b> Action Bar Buttons (page 17).

## 3.2.3 Icon and Buttons

### 3.2.3.1 Status Message Icons

Status messages are displayed by means of small icons in the status bar. For the most important messages **see** Status Messages (page 95).

By tapping the symbols, the explanation of the symbols will appear in a separate window.

### 3.2.3.2 Title Bar Icons

The title bar icons only appear when they are active. The icons which appear in the title bar, are listed with their function below:

	Explanation
	Create a shortcut and add it to your user home screen. Edit or remove an existing shortcut <b>see</b> Using Shortcuts (page 83).

### 3.2.3.3 Action Bar Buttons

The action bar contains action buttons for triggering any of the actions which are required and available in the current dialog (e.g. **Back**, **->O/T<-**, **Print**, **Save**, **Delete**, **OK**). There are up to six action buttons available for a work step. The functions of these buttons are self explanatory and therefore not discussed further.

## 3.2.4 Input Dialogs

### 3.2.4.1 Entering Text and Numbers

The keyboard dialog allows you to enter characters including letters, numbers and a variety of special characters. The country-specific layout of the keyboard is in accordance with the selected language, **see** Regional Settings (page 36).



	Name	Explanation
1	Input field	
2	Explanation field	The maximum number of characters allowed is indicated.
3	Shift	You can enter lower and upper case letters by toggling ☰. Switch the keyboard by tapping the corresponding button in the action bar, for entering numbers, special characters or letters

- Confirm with [OK] (To exit keyboard tap [Cancel]).


	Function
☰	Shift-Lock
☒	Delete last character
↶	Cursor left
↷	Cursor right

#### Note

It is also possible to place cursor directly in input field by tapping the respective position.

### 3.2.4.2 Entering Numerical Values

The numerical keypad dialog allows you to enter numerical values.



	Name	Explanation
1	Switch	If a switch appears, located on the left side in the title bar; it must be switched on for the entry of a value: O = OFF, I = ON
2	Input field	
3	Explanation field	The valid input range is indicated.

– Confirm with [OK].

To exit keypad, tap [Cancel].

	Function
	Delete last character
	Cursor left
	Cursor right

### 3.2.4.3 Changing Date and Time

This dialog (Picker view) allows you to set the date and time by picking from the built-in calendar/clock.

The screenshot shows a Date Picker dialog with the following interface:

- Top Bar:** Shows "Administrator" on the left and "4. Oct 2011 - 11:14" on the right.
- Title Bar:** Labeled "Date".
- Date Selection Area:** A horizontal slider with three pick buttons (+, +, +) and a central value field showing "4".
  - Control 1:** The first pick button on the left.
  - Control 2:** The value field containing "4".
  - Control 3:** The third pick button on the right.
- Month/Year Selection Area:** A horizontal slider with three pick buttons (-, -, -) and a central value field showing "Oct 2011".
- Buttons at the bottom:** "Cancel" on the left and "Set date" on the right.

	Name	Explanation
<b>1</b>	Pick button	Pick button upwards (input control)
<b>2</b>	Explanation field	Current value
<b>3</b>	Pick button	Pick button downwards (input control)

- Confirm with [**Set date**]. (To exit without changing, tap [**Cancel**].)

### 3.2.5 Lists and Tables

#### Simple list view

Basic elements of a simple list including a content title. If necessary, the content area can be scrolled vertically and can be arranged in a different order.



	Name	Explanation
1	Content title	
2	Content area	
3	Arrow icon	[↓] Showing the list in ascending order. [↑] Showing the list in descending order.
4	Scrollbar	Scrolling up
5		Scroller
6		Scrolling down

Further types of lists:

Accordion panels can be opened or closed by tapping [↗].


Closable panels can be opened or closed by tapping [>].

### 3.2.6 Work Screen

The work screen is used for performing main tasks e.g. measurements.



Name	Explanation
1 Name field	Name of current Method
2 Shortcut button	Adding/editing a shortcut to the home screen for this method
3 Value panel	Displays the current measured values of the work process
4 Graphics panel	E.g. graphical illustrations of the drying curves, instructions for the user for performing tasks, and weighing-in aid
5 ID panel	Identifications (IDs) appear after tapping the ID panel for entering or editing values (comments). ID panel appears only if identification input is activated in the menu.
6 Parameter panel	Displays the parameters of the current work process. A detailed overview of the method parameters appears after tapping the parameter panel.
7 Action buttons	Depending on the current context



Measurement in progress

### 3.2.7 Graphics View



Graphical view of single measurement




Chart view of series of measurements

For further information **see** Graphical Evaluations of Measurement Results (page 85)

## 4 Installation and Putting into Operation

In this section you will find information how to put your new instrument into operation.

### 4.1 Scope of Delivery

Open the package and remove drying unit, terminal and the accessories. Check the completeness of the delivery. The following accessories are part of the standard equipment of your new Moisture Analyzer:

- 80 aluminum sample pans
- 1 sample handler
- 1 sample pan holder
- 1 specimen sample (circular, absorbent glass fibre filter)
- 1 draft shield
- 1 power cable (country specific)
- 1 Terminal cable (Interface Terminal – drying unit)
- 1 Operating instructions
- 1 Application brochure «Guide to Moisture Analysis»
- 1 Production certificate
- 1 Declaration of conformity

Remove the packaging from the instrument. Check the instrument for transport damage. Immediately inform your METTLER TOLEDO representative if you have any complaints or parts are missing.


#### Note

Store all parts of the packaging. This packaging guarantees the best possible protection for the transport of your instrument.

### 4.2 Location

Your Moisture Analyzer is a precision instrument. An optimum location guarantees accuracy and dependability. Make sure that the following environmental conditions are met:

- Operate the instrument only indoors and at an altitude of less than 4000 m above sea level.
- Before switching on the instrument, allow all its parts to reach room temperature (+5 to 30°C).  
Make sure that the relative humidity is between 20% and 80% and non-condensing conditions are met.
- The power plug must be easily accessible.
- Firm, horizontal location as free from vibrations as possible.
- Avoid direct sunlight.
- No excessive temperature fluctuations.
- No powerful drafts.
- Surroundings as free from dust as possible.
- Sufficient clearance around the instrument to allow warm air to dissipate.
- Sufficient distance from heat-sensitive materials in the vicinity of the instrument.



---

**WARNING****Substances which contain toxic or caustic components**

Toxic gases produced during drying could cause irritations (eyes, Skin, breathing), illness or death.

- Such substances may be dried only in a fume cupboard.
- 

## 4.3 Opening and Closing Sample Chamber

Open and close the sample chamber exclusively by pressing the [**↑**] key.

**Attention**

Do not open the sample chamber manually.

Only manually opening the sample chamber in emergency situation:

- 1 Hold the handles on the heating module **with both hands** and pull the module firmly upwards to open the sample chamber.
- 2 Pull out the power plug.

**Note**

It is necessary to reboot the system, after an emergency opening.

## 4.4 Connecting Instrument

---

**WARNING****Risk of electric shock**

- a) Use only the 3-pin power cable with equipment grounding conductor which was supplied with your instrument.
  - b) Only an 3-pin grounded outlet for connecting your instrument must be used.
  - c) Only extension cables which meet this relevant standards and also have an equipment grounding conductor may be used.
  - d) Intentional disconnection of the equipment grounding conductor is prohibited.
- 

**Attention**

- First, check whether the voltage printed on the type plate of the drying unit matches your local line voltage. If this is not the case, on no account connect the drying unit to the power, but contact your METTLER TOLEDO sales representative or dealer.

Two different versions of drying units with country-specific power cable are available (110 V AC or 230 V AC).

- The power plug must be always accessible.
- Before operating, check all cables for damage.
- Guide the cables so that they cannot become damaged or interfere with the measuring process.

**Connecting the Terminal to the Drying Unit**


- Drying unit and terminal are at the final location.

- 1 Connect one end of the supplied terminal cable to the system connection socket on the terminal, **see Terminal** (page 12).
- 2 Screw the connector firmly.
- 3 Connect the other end to the system connection socket on the drying unit, **see Drying Unit** (page 11).
- 4 Screw the connector firmly.

## Connecting the Drying Unit to the Power Supply

- Terminal – drying unit interface is connected.
- 1 Connect one end of the power cable to the power supply socket on the drying unit, **see** Drying Unit (page 11).
  - 2 Connect the other end to the power line outlet.

## 4.5 Setting up Drying Unit



- Terminal and drying unit are connected.
- 1 Switch on the Instrument by pressing [**⑤**].
  - 2 Press [**↑↓**].  
⇒ the motorized automatic sample chamber opens.
  - 3 Place the draft shield element (1). Only one position is possible.
  - 4 Insert the sample pan holder (2) carefully. Check that the sample pan holder is hooked correctly.
  - 5 Insert the sample pan handler (3).

### Attention

The drying unit is specially designed for motorized opening or closing of the sample chamber.  
Do not open the sample chamber manually. Only open manually in emergency situations. In all other cases use always the [**↑↓**] key, **see** Keys on the Terminal (page 14).

### Note

When putting into operation for the first time or if the instrument is disconnected from the power supply over a longer period, leave the instrument connected to the power supply for at least 5 hours to allow the built-in rechargeable battery to charge up! This battery ensures that the date and time are not lost when the instrument is dis-

connected from the power. This battery can not be replaced by the user. Please contact a METTLER TOLEDO representative.

## 4.6 Leveling Drying Unit


Exact horizontal positioning and stable installation are prerequisites for repeatable and accurate results. To compensate for small irregularities or inclinations ( $\pm 2\%$ ) at the location, the instrument must be leveled.

For exact horizontal positioning, the drying unit has a level indicator (level) and 2 leveling screws. When the air bubble in the level indicator is exactly in the center, the instrument is standing perfectly horizontally. To level it, proceed as follows:

- 1 Position your Moisture Analyzer at the selected location.
- 2 Turn the two leveling feet until the air bubble is in the center of the level indicator.

L = left foot


R = right foot



Air bubble at	"12 o'clock"	turn both feet clockwise
Air bubble at	"3 o'clock"	turn left foot clockwise, right foot counterclockwise
Air bubble at	"6 o'clock"	turn both feet counter-clockwise
Air bubble at	"9 o'clock"	turn left foot counterclockwise, right foot clockwise

**Note**


The drying unit should be re-leveled each time its location is changed.



### Leveling the drying unit with optional stand for terminal mounted.

Stand for terminal **see** Accessories and Spare Parts (page 105).

- The drying unit is positioned at the selected location.
- 1 To loose the clamps for the safety feet of the stand, turn them outwards.
  - 2 Level the drying unit as previously described.
  - 3 To lock the clamps for the safety feet, turn them inwards as far as they will go.



#### Level sensor


The built-in level sensor constantly monitors the correct horizontal alignment of the drying unit. When the level is incorrect, the status icon ⓘ appears in the display, **see** Status Message Icons (page 17).

#### Note

The level sensor cannot be switched off.


## 4.7 Anti-theft Device

For protection against theft, your drying unit is fitted with a Kensington security slot for an anti-theft device. To find a suitable anti-theft cable **see** Accessories and Spare Parts (page 105).



## 4.8 Setting Reading Angle of Terminal

- To change the reading angle, fold out the two tilt feet.



## 4.9 Setting Date and Time

#### Navigation: Home > Settings > System settings > Regional Settings

When you put your new instrument into operation for the first time, you should enter the current date and time. These settings are retained even if you disconnect your instrument from the power supply.

#### Note

Various languages are available for the dialog with your instrument and can be selected in the menu:

**Navigation: Settings > User preferences, see** User Preferences (page 34).

#### **Set the current date**

- **Regional Settings** is selected.

- 1 Tap **Date**.
- 2 Set day, month and year.
- 3 Confirm with [**Set date**].

#### **Set the current time**

- **Regional Settings** is selected.

- 1 Tap **Time**.
- 2 Set Hours and minutes.
- 3 Confirm with [**Set time**].

#### **Note**

For changing the format for date and time, **see** Regional Settings (page 36).

## **4.10 Adjustment**

To obtain accurate measuring results, it is necessary to adjust the integrated balance as well as the heating module.

Adjusting is necessary:

- before the instrument is used for the first time.
- at regular intervals.
- after a change of location.

The following adjustment options are possible:

- Fully automatic balance adjustment FACT.
- Balance adjustment with internal weight.
- Balance adjustment with external weight (accessory).
- Temperature adjustment with temperature adjustment kit (accessory).

For more information to perform these operations **see** Test/Adjust (page 55).

## 5 My First Measurement

After you have successfully put your new Moisture Analyzer into operation for the first time, you can immediately perform your first measurement. In doing so, you will become familiar with the instrument.

Use the supplied specimen sample (absorbent glass fiber filter) for your first measurement to determine the moisture content. During your first measurement the instrument operates with the factory settings.

### Switch on

- The instrument is connected to the mains.
- To switch on, press [].



### Create a method


- 1 Tap **Method Definition**.  
⇒ **Method Definition** menu appears.
- 2 To define a new method, tap [**New...**].  
⇒ The keypad appears.
- 3 Enter a name for your first method e.g. **My first method**.
- 4 Confirm with [**OK**].
- 5 To store your new method with factory settings, tap [**Save**].
- 6 Tap [**Home**].  
⇒ User home screen appears.

### Select the method for measuring

- 1 Tap [**Measurement**].  
⇒ The methods list is displayed.
- 2 Tap **My first method**.  
⇒ The work screen of the method **My first method** appears.  
⇒ The sample chamber opens automatically.

### Placing sample pan

- The display now prompts you to load the empty sample pan and tare the balance.
- 1 Place the empty sample pan in the sample pan handler.
  - 2 Place the sample pan handler in the sample chamber. Ensure that the tongue of the pan handler fits exactly in the slot of the draft shield element. The sample pan must lie flat in the pan holder.



### Note

We advise you to work with the sample pan handler at all times. The pan handler is ergonomic, automatic positioning, safe and provides protection against possible burns due to the hot sample pan.


### Taring balance

- Tap [ ->0/T<- ].
  - ⇒ The sample chamber closes automatically for taring.
  - ⇒ When taring is completed, the sample chamber opens automatically.



### Start measuring

- Following taring, the display prompts you to add the sample to the sample pan.
  - 1 Place the specimen sample (glass fibre filter) in the sample pan.
  - 2 Wet the specimen sample with a few drops of water.
  - 3 Tap [**Start drying**]
    - ⇒ The sample chamber closes automatically.
    - ⇒ The drying process starts automatically.



### Drying process

You can follow the measurement process on the display, **see** Work Screen (page 22).

- The drying process is continuously displayed graphically.
- The current temperature in the heating module is displayed as well as the elapsed drying time and the current drying value.
- The display shows the selected settings.
- The drying process can be aborted by tapping [**Stop drying**].

At the end of the drying process you can read the moisture content of your sample on the display. If you have defined the control limits in the method, passed, warned or failed status is shown.

### Remove Sample


#### CAUTION



#### Danger of burns

Sample, sample pan and sample pan holder may still be hot.

- The drying process is completed.
  - The sample chamber is open (opens automatically after the measurement is completed).
- 1 Carefully remove the sample pan handler from the sample chamber.
- Note**
- To remove the sample pan from the handler, lift the pan slightly from below and remove it from the handler.
- 2 • To perform a further measurement with the current method, tap [**Next Sample**].
    - To perform a measurement with a new method, tap [**Measurement**].
    - To return to the home screen, press [].



### Congratulations!

You have just performed your first measurement with your new Moisture Analyzer. In the following sections you will find more information about the extensive functions of this instrument.

## 6 Settings

**Navigation:** Home > Settings

In this section you will find information how to define the general settings of your instrument.

### Menu structure

Main menu	Submenu	Further information
<b>User preferences</b>	<b>Languages</b>	<b>see Languages (page 34)</b>
	<b>Screen</b>	<b>see Screen (page 34)</b>
	<b>Sound</b>	<b>see Sound (page 34)</b>
	<b>Password</b>	<b>see Password (page 35)</b>
<b>System settings</b>	<b>Regional Settings</b>	<b>see Regional Settings (page 36)</b>
	<b>Peripherals</b>	<b>see Peripherals (page 36)</b>
	<b>Default settings</b>	<b>see Default Settings (page 37)</b>
	<b>Touch screen adjustment</b>	<b>see Touch Screen Adjustment (page 38)</b>
<b>Application settings</b>	<b>Identifications management</b>	<b>see Identifications Management (page 40)</b>
	<b>Print and output management</b>	<b>see Print and Output Management (page 40)</b>
<b>Quality management</b>	<b>Test / Adjustment settings</b>	<b>see Test / Adjustment settings (page 42)</b>
<b>User management</b>	<b>Groups</b>	<b>see Groups (page 46)</b>
	<b>Users</b>	<b>see Users (page 48)</b>
	<b>Account policies</b>	<b>see Account Policies (page 49)</b>
<b>System and data management</b>	<b>Export / Import</b>	<b>see Export / Import (page 50)</b>
	<b>Back up / Restore</b>	<b>see Back up / Restore (page 51)</b>
	<b>Reset</b>	<b>see Reset (page 52)</b>
	<b>Update</b>	<b>see Update (page 52)</b>

## 6.1 User Preferences

### Navigation: Home > Settings > User preferences

This menu item defines the basic settings for each user. These settings are stored under the active user profile and apply when working within this profile. When a user profile is called up (login user account), the relevant settings are loaded automatically. **See** User Management (page 46).

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Languages</b>	Defines your preferred display and keyboard language.	<b>see</b> Languages (page 34)
<b>Screen</b>	Defines the brightness and the color scheme of the display	<b>see</b> Screen (page 34)

### 6.1.1 Languages

#### Navigation: Home > Settings > User preferences > Languages

Select your preferred language for operating the terminal.

**Factory setting:** Generally, the language of the destination country (if available) or English is set.

You can define the following parameters:

Parameter	Explanation	Values
<b>Display language</b>	Defines user-specific screen language.	<b>English   Deutsch   Italiano   Français   Español   Português   Polski   Magyar   Český   Русский   日本語   中文   한국어/조선말</b>
<b>Keyboard language</b>	Defines user-specific layout of the Keypad.	<b>English   Deutsch   Italiano   Français   Español   Português   Polski   Magyar   Český</b>

### 6.1.2 Screen

#### Navigation: Home > Settings > User preferences > Screen

You can define the following parameters:

Parameter	Explanation	Values
<b>Brightness</b>	Defines user-specific brightness of the display.	10...100 % (80 %)*
<b>Color scheme</b>	Defines user-specific display color scheme.	<b>Blue*   Green   Orange   Grey</b>

\* Factory setting

### 6.1.3 Sound

#### Navigation: Home > Settings > User preferences > Sound

You can define the following parameters:

Parameter	Explanation	Values
<b>Sound</b>	Activate / deactivate of audible feedback and adjust the volume. Audible feedback: <ul style="list-style-type: none"> <li>• when tapping a button.</li> <li>• upon measurement completed.</li> <li>• before automatic closing of the sample chamber.</li> <li>• when an error message appears.</li> </ul>	<b>OFF*</b>   <b>ON</b>   0...100 % (50 %)*

\* Factory setting

#### 6.1.4 Password

**Navigation:** Home > Settings > User preferences > Password

In this menu item you can change the user password. It is also possible to create a password for protection or to deactivate the password protection.

You can define the following parameters:

Parameter	Explanation	Values
<b>Password</b>	Change an existing or create a new password. <b>OFF</b> = no password protection.	<b>OFF</b>   <b>any</b>

## 6.2 System Settings

**Navigation:** Home > Settings > System settings

This menu item defines the basic settings for the system. The system settings apply to the entire system and therefore to all user profiles and applications.

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Regional settings</b>	Defines the settings of date & time and keypad country options.	<b>see</b> Regional Settings (page 36)
<b>Peripherals</b>	Defines the configuration of printers and other devices.	<b>see</b> Peripherals (page 36)
<b>Default settings</b>	Defines the default settings of your instrument.	<b>see</b> Default Settings (page 37)
<b>Touch screen adjustment</b>	Adjusts the touch screen.	<b>see</b> Touch Screen Adjustment (page 38)

### 6.2.1 Regional Settings

**Navigation:** Home > Settings > System settings > Regional Settings

This menu item defines the settings of date & time.

You can define the following parameters:

Parameter	Explanation	Values
<b>Date</b>	Sets the date of the clock of the instrument.	<b>Day   Month   Year</b>
<b>Time</b>	Sets the clock time of the instrument.	<b>Hours   Minutes</b>
<b>Date format</b>	Defines the date format. D = Day M = Month Y = Year	<b>D. MMM YYYY*  </b> <b>MMM D YYYY  </b> <b>DD.MM.YYYY  </b> <b>MM/DD/YYYY  </b> <b>YYYY/MM/DD  </b> <b>YYYY-MM-DD</b>
<b>Time format</b>	Defines the time format. M = Minutes	<b>24:MM*   12:MM  </b> <b>24.MM   12.MM</b>

\* Factory setting

#### Note

Date and time of a connected printer will be ignored. Date and time of instrument is relevant.

### 6.2.2 Peripherals

**Navigation:** Home > Settings > System settings > Peripherals

In this menu item you can configure one printer and one host connection.

#### Remote clients

The **MT-SICS** host connection (remote client) is enabled by default and only usable with the METTLER TOLEDO specific protocol MT-SICS.

MT-SICS commands and functions can be transmitted via the RS232 interface (COM1 port) or the USB device interface (COM4 port). The use of the USB device interface requires the installation of an USB device driver on the PC, **see** Installing USB Device Driver (page 111).

Commands and further information please refer to the Reference Manual **MT-SICS Interface Commands for Halogen Moisture Analyzers** downloadable from the internet.

► [www.mt.com/hxhs](http://www.mt.com/hxhs)

## Printers

No printer is installed by default. To install a printer:

- 1 Tap [**New...**]  
⇒ **Peripheral type** list appears.
- 2 Select device.  
**Note**  
Currently supported devices from METTLER TOLEDO with preset parameters:
  - **RS-P42 Strip Printer**
  - **RS-P25 Strip Printer**
  - **LabX Direct Moisture**
- 3 Set the parameters.
- 4 To store the settings, tap [**Save**].
- 5 To activate the interface, tap [**ON**].  
⇒ Status changes from **Disabled** to **Enabled**.

### Note

- A printer or host connection can also be deleted.
- For printer settings **see** Recommended Printer Settings (page 110).
- For defining the printouts **see** Print and Output Management (page 40).

You can define the following parameters:

Parameter	Explanation	Values
<b>Device Name</b>	Defines a name for the device.	<b>any</b>
<b>Device Port</b>	Defines the device port. <b>COM1</b> : RS232 / <b>COM4</b> : USB Device (Driver required) <b>Note</b> It is possible to use an USB-to-Serial adapter. If such an adapter is connected, these devices are shown as e.g. <b>SOU1</b> , <b>SOU2</b> (SOU stands for serial over USB)	<b>COM1*   COM 4</b>
<b>Baudrate</b>	Defines the speed of the data transmission (date transfer rate / Baud rate).	<b>1200   2400   4800   9600*   19200   38400   57600   115200</b>
<b>DataBits</b>	Defines the number of data bits.	<b>7   8*</b>
<b>Parity</b>	Defines the variant of parity bit.	<b>None*   Odd   Even</b>
<b>StopBits</b>	Defines the stop bits of the transmitted data.	<b>1 StopBit*   2 StopBits</b>
<b>Flow Control</b>	Defines the type of flow control (Handshake).	<b>None   Hardware   Xon/Xoff*</b>

\* Factory setting

### 6.2.3 Default Settings

**Navigation:** Home > Settings > System settings > Default settings

Define the default settings of your instrument.

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Default lan-guages</b>	Defines a default display and keyboard language.	<b>see</b> Default Languages (page 38)
<b>Default screen settings</b>	Defines the default brightness and color scheme.	<b>see</b> Default Screen Settings (page 38)

### 6.2.3.1 Default Languages

**Navigation:** Home > Settings > System settings > Default settings > Default languages

Select the default language for operating the terminal. Factory setting: Generally, the language of the destination country (if available) or English is set.

You can define the following parameters:

Parameter	Explanation	Values
<b>Default display language</b>	Defines default screen language.	English   Deutsch   Italiano   Français   Español   Português   Polski   Magyar   Český   Русский   日本語   中文   한국어/조선말
<b>Default keyboard language</b>	Defines default layout of the keyboard.	English   Deutsch   Italiano   Français   Español   Português   Polski   Magyar   Český

### 6.2.3.2 Default Screen Settings

**Navigation:** Home > Settings > System settings > Default settings > Default screen settings

You can define the following parameters:

Parameter	Explanation	Values
<b>Brightness</b>	Defines default brightness of the display.	10...100 % (80 %)*
<b>Color scheme</b>	Defines default display color scheme.	Blue*   Green   Orange   Grey

\* Factory setting

### 6.2.4 Touch Screen Adjustment

**Navigation:** Home > Settings > System settings > Touch screen adjustment

If the alignment of the touch-sensitive areas of the screen correspond not exactly with the position of the buttons e.g. after a software update was performed, then you can solve this error by executing this function.

---

**CAUTION**




**Do not touch the touch screen with pointed or sharp objects!**

This may damage the touch screen.

---

- ▶ Menu **System settings** appears.
- 1 Choose **Touch screen adjustment** and tap [**Start**].  
⇒ Adjustment screen appears.
  - 2 Touch and hold a touch screen stylus (resistive) on the center of the target until it moves to the next position on the screen.
  - 3 Repeat this procedure until a message appears (**New calibration settings have been measured**).
  - 4 Tap the screen to confirm or wait for 30 seconds to cancel (time-out).  
⇒ A message box appears.
  - 5 To store the setting, tap [**OK**].



#### Note

- Tap the center of the target as exact as possible otherwise the process has to be repeated several times.
- Make sure not to touch any other locations on the screen and the fix key areas while doing this adjustment.
- Make sure not to touch the screen with your hand.
- Ensure minimum viewing angle.
- The adjustment process cannot be aborted.

## 6.3 Applications Settings

**Navigation:** Home > Settings > Application settings

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Identifications management</b>	Defines identifications and their use in order to comment measurements.	<b>see</b> Identifications Management (page 40).
<b>Print and output management</b>	Defines the default settings for the printouts.	<b>see</b> Print and Output Management (page 40).

### 6.3.1 Identifications Management

**Navigation:** Home > Settings > Application settings > Identifications management

Identifications (ID) contain descriptive text for individual measurements, which enables samples to be easily allocated to specific tasks or customers. This feature allows you to define identifications in order to comment measurements, such as company id, id badge, id sample. In the ID panel on the work screen, the values (comments) can be entered or changed before measurement, **see** Work Screen (page 22). IDs have an impact on all measurements, regardless of methods. The IDs are included on printouts or can be exported to a PC.

**Menu structure**

Main menu	Submenu	Further information
<b>Identifications usage</b>	<b>Identifications input</b>	<b>see</b> below
	<b>Clear input after measurement</b>	
<b>Identifications</b>	no submenu	

You can define the following parameters:

Parameter	Explanation	Values
<b>Identifications input</b>	Defines the method for entering comments. <b>ON</b> = activates ID panel on work screen. <b>Free input</b> = the IDs appear after tapping on the ID panel (work screen) for entries or changes of values (comments). <b>Guided input</b> = each ID is displayed individually in order of definition (ID1 to ID10) before measurement, to make entries or changes of values (comments).	<b>OFF*</b>   <b>ON</b>   <b>Free input</b>   <b>Guided input</b>
<b>Clear input after measurement</b>	Defines the ID whose value (comment) is deleted after measurement.	<b>OFF*</b>   <b>ON</b>   ID selection: <input type="checkbox"/>   <input checked="" type="checkbox"/>
<b>Identifications</b>	Defines general identifications in order to comment measurements. + = New identifications (max. 10 IDs, 1...20 characters) - = Remove identifications (selectable)	+   -

\* Factory setting

### 6.3.2 Print and Output Management

**Navigation:** Home > Settings > Application settings > Print and output management

If a printer is connected and activated, results can be automatically printed out. The interim values are printed out in the pre-selected intervals and the final results are logged at the completion of the measurement. The printout contains information to the instrument, time, date as well as the method and results, depending of the protocol. The level of detail depends on the selected type of printout (short, standard) and the activated protocol items (settings or method), **see** Information on Printouts (page 87).

**Note**

- The definitions in this menu item are the default settings for the printouts. These parameters are displayed at every initialization of a Printout and can be modified again.
- The setting for printout language in this menu item has no impact on test or adjustment printouts, **see** Print and Output Settings (page 44).
- Not all languages are compatible with some printers, and also depending on the settings of the printer, **see** Recommended Printer Settings (page 110).
- For installing and defining a printer **see** Peripherals (page 36).

You can define the following parameters:

Parameter	Explanation	Values
<b>Printout type</b>	Selects a detailed printout or in a short form.	<b>Standard*</b>   <b>Short</b>
<b>Printout language</b>	Defines the language for general printouts.  <b>Note</b> No impact on test or adjustment printouts.	<b>English</b>   <b>Deutsch</b>   <b>Italiano</b>   <b>Français</b>   <b>Español</b>   <b>Português</b>   <b>Polski</b>   <b>Magyar</b>   <b>Český</b>
<b>Print results automatically after measurement</b>	Print results automatically after measurement if activated.	<input type="checkbox"/> (deactivated)*   <input checked="" type="checkbox"/> (activated)
<b>Include intermediate results to printout</b>	Defines the time intervals at which interim results are transferred to the printer.	<b>OFF*</b>   <b>10 s</b>   <b>30 s</b>   <b>1 min</b>   <b>2 min</b>   <b>10 min</b>

\* Factory setting

## 6.4 Quality Management

**Navigation:** Home > Settings > Quality management

In this menu you can define all settings related to the adjustment and Test of the instrument. Periodic adjustments or tests ensure accurate measurement results.

You can define the following parameters:

Menu item	Explanation	Further Information
Test / Adjustment settings	Defines the equipment for adjusting and the workflow for testing or adjusting.	<b>see</b> Test / Adjustment settings (page 42)

### 6.4.1 Test / Adjustment settings

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings

This section describes all the menu options available for defining the parameters relating to the adjustment and testing of your instrument.

For performing test and adjustments **see** Test/Adjust (page 55).

**Menu structure**

Main menu	Submenu	Further information
Equipment	Test weight 1	<b>see</b> Equipment (page 42)
	Test weight 2	
	Temperature kit	
Test settings	Weight test - internal	<b>see</b> Test Settings (page 43)
	Weight test - external	
	Temperature test	
Adjustment settings	Weight adjustment - internal	No adjustable settings available
	Weight adjustment - external	<b>see</b> Adjustment Settings (page 44)
	Temperature adjustment	
Print and output settings	Printout language	<b>see</b> Print and Output Settings (page 44)
	Print results automatically after test/adjustment	
FACT	no submenu	<b>see</b> FACT (Fully automatic adjustment) (page 45)

#### 6.4.1.1 Equipment

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings > Equipment

This menu item defines the equipment needed for weight adjustment, weight test, temperature adjustment or temperature test.

##### Note

For performing temperature adjustment or temperature test, you need the optional temperature adjustment kit, **see** Accessories and Spare Parts (page 105).

##### Test Weight 1 and Test Weight 2

You can define the following parameters:

Parameter	Explanation	Values
<b>Temperature kit name</b>	Defines a name that is in an easily recognizable form as an alternative to the ID. A name should be unique and unambiguous.	any
<b>Nominal weight</b>	Defines the nominal weight in grams.	30.000...200.000 g (200 g)*
<b>Identification</b>	Defines the identification (ID) of the weight. The ID of the weight is provided on the Weight Certificate. The ID may contain your company specific identification number. This ID is stored in the adjustment or test history and shows up on the printouts.	any

\* Factory setting

### Temperature Adjustment Kit

You can define the following parameters:

Parameter	Explanation	Values
<b>Temperature kit name</b>	Defines a name that is in an easily recognizable form as an alternative to the ID. A name should be unique and unambiguous.	any
<b>Identification</b>	Defines the identification (ID) of the Temperature kit. The ID is provided on the Certificate. The ID may contain your company specific identification number. This ID is stored in the adjustment or test history and shows up on the printouts.	any

#### 6.4.1.2 Test Settings

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings > Test settings

##### Weight test internal

You can define the following parameters:

Parameter	Explanation	Values
<b>Tolerance</b>	Defines the measuring tolerance of the internal weight.	0...1 % (0.001 %)*

##### Weight test external

You can define the following parameters:

Parameter	Explanation	Values
<b>Test weight</b>	Selects the predefined <b>Test weight</b> . <b>Test weight 1 / Test weight 2</b> = defined in the menu item <b>Equipment</b>	<b>Test weight 1</b>   <b>Test weight 2</b>
<b>Tolerance</b>	Defines the measuring tolerance of the weight.	0.0001...0.1000 g (0.0010 g)*

\* Factory setting

##### Temperature test

You can define the following parameters:

Parameter	Explanation	Values
<b>Temperature kit</b>	Shows the name of the <b>Temperature kit</b> which was defined in the menu item <b>Equipment</b> .	none
<b>Temperature 1</b>	Defines the lower test temperature. The value is based on the lower adjustment temperature and is not editable in the temperature test.	<b>OFF</b>   <b>ON</b> (100 °C)*
<b>Tolerance</b>	Defines the tolerance of the test temperature.	1...5 °C (3 °C)*
<b>Temperature 2</b>	Defines the upper test temperature The Value is based on the upper adjustment temperature.	<b>OFF</b>   <b>ON</b> (160 °C)*

<b>Tolerance</b>	Defines the tolerance of the test temperature.	1...5 °C (3 °C)*
<b>Temperature 3 (additional)</b>	Defines an additional Test temperature.	<b>OFF*   ON  </b> 60...200 °C
<b>Tolerance</b>	Defines the tolerance of the test temperature.	1...5 °C (3 °C)*

\* Factory setting

#### 6.4.1.3 Adjustment Settings

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings > Adjustment settings

##### Weight adjustment internal

No editable parameters.

##### Weight adjustment external

You can define the following parameters:

Parameter	Explanation	Values
<b>Test weight</b>	Selects the predefined <b>Test weight</b> . <b>Test weight 1 / Test weight 2</b> = defined in the menu item <b>Equipment</b>	<b>Test weight 1  </b> <b>Test weight 2</b>

##### Temperature adjustment

You can define the following parameters:

Parameter	Explanation	Values
<b>Temperature kit</b>	Shows the name of the <b>Temperature kit</b> which was defined in the menu item <b>Equipment</b> .	none
<b>Temperature 1</b>	Defines the lower temperature.	80...140 °C (100 °C)*
<b>Temperature 2</b>	Defines the upper temperature	140...200 °C (160 °C)*

\* Factory setting

##### Note

Most samples are measured in the range of 100 °C and 160 °C. This is also the factory setting. The range can be expanded to the range of 80°C and 200°C. The difference between the lower and upper temperature has to be equal or more than 60 °C.

#### 6.4.1.4 Print and Output Settings

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings > Print and output settings

This menu item allows you to set specific printer functions for test or adjustment printouts.

- The setting for printout language in this menu item has impact on test or adjustment printouts only. For setting the general printout language, see Print and Output Management (page 40).
- Not all languages are compatible with any printer, and also depending on the settings of the printer, see Recommended Printer Settings (page 110).
- For installing and defining a printer see Peripherals (page 36).

You can define the following parameters:

Parameter	Explanation	Values
<b>Printout language</b>	Defines the printout language for test or adjustment printouts.	<b>English   Deutsch   Italiano   Français   Español   Português   Polski   Magyar   Český</b>
<b>Print results automatically after test/adjustment</b>	Activated or deactivated function.	<input checked="" type="checkbox"/> (enabled)*   <input type="checkbox"/> (disabled)

\* Factory setting

#### 6.4.1.5 FACT (Fully automatic adjustment)

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings > FACT

This menu item allows you to deactivate or activate fully automatic adjustment function **FACT**.

##### Note

- Before performing an external weight adjustment, we recommend you to disable **FACT**. Otherwise **FACT** overwrites the adjustment.
- This function is not available for approved models – that is, **FACT** is always active.

You can define the following parameters:

Parameter	Explanation	Values
<b>FACT</b>	Enabled or disabled fully automatic adjustment <b>FACT</b> function.	<input checked="" type="checkbox"/> (enabled)*   <input type="checkbox"/> (disabled)

\* Factory setting

## 6.5 User Management

### Navigation: Home > Settings > User management

The security system of the instrument is based on a "Users and Groups" concept. Every real user of the instrument should be represented by a user account on the instrument which holds particular settings of the respective user. Every user belongs to a particular group and inherits the access rights assigned to that group.

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Groups</b>	Defines groups and their access rights.	<b>see</b> Groups (page 46)
<b>Users</b>	Defines the user accounts.	<b>see</b> Users (page 48)
<b>Account policies</b>	Set default startup user.	<b>see</b> Account Policies (page 49)

### 6.5.1 Groups

#### Navigation: Home > Settings > User management > Groups

In this menu you can create, delete, or edit user groups and define their access rights.

Four predefined groups are available. The default group with all access rights is administrator. The administrator group can not be edited or deleted. All other groups can be edited or deleted.

Predefined groups	Default access rights						
	User Preference settings	System settings	Edit Methods	Run Tests	Run Adjustments	Quality management	User and data management
Administrator	<input checked="" type="checkbox"/>						
Supervisor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
Quality Manager	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Operator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Creating a new group

- Menu **Groups** selected.
- 1 Tap [**New...**].
- 2 Enter the name of the new group and confirm with [**OK**]. Name should be unique and unambiguous.
- 3 Edit the properties of the new group.

#### Deleting a group

- Menu **Groups** selected.
- 1 Select the group you wish to delete.
- 2 Tap [**Delete**]. Confirm the message box.

#### Note

The Administrator group as well as groups with assigned users cannot be deleted, **see** Users (page 48).

#### Editing a group

- Menu **Groups** selected.
- 1 Select the group you wish to edit.
- 2 Edit the group parameters. Store the settings with [**Save**].

You can define the following parameters:

Parameter	Explanation	Values
<b>Group properties</b>	Name and (optional) description of the group. Name should be unique and unambiguous.	<b>any</b>
<b>Access rights</b>	Defines the access rights to menus or operations.	<b>User Preference settings   System settings   Edit Methods   Run Tests   Run Adjustments   Quality Management   User and data management</b>
<b>Group members</b>	Displays the users assigned to this group (no editing can be done here, the assignment is done when setting up or editing a user).	<b>none</b>
<b>History</b>	Displays the date and time of the last modifications made to this group (no editing here).	<b>none</b>

#### Influence of access rights

Access rights	Impact on
<b>User Preference settings</b>	<b>User preferences</b> <b>Navigation: Home &gt; Settings &gt; User preferences</b> <b>See User Preferences (page 34)</b>
<b>System settings</b>	<b>System settings</b> <b>Navigation: Home &gt; Settings &gt; System settings</b> <b>See System Settings (page 36)</b>
<b>Edit Methods</b>	<b>Method definition</b> <b>Navigation: Home &gt; Method definition</b> <b>See Method Definition (page 64)</b>
	<b>Application settings</b> <b>Navigation: Home &gt; Settings &gt; Application settings</b> <b>See Applications Settings (page 40)</b>
<b>Run Tests</b>	<b>Tests</b> <b>Navigation: Home &gt; Test/Adjust &gt; Tests</b> <b>See Tests (page 60)</b>
<b>Run Adjustments</b>	<b>Adjustments</b> <b>Navigation: Home &gt; Test/Adjust &gt; Adjustments</b> <b>See Adjustments (page 55)</b>
<b>Quality management</b>	<b>Quality management</b> <b>Navigation: Home &gt; Settings &gt; Quality management</b> <b>See Quality Management (page 42)</b>
<b>User and data management</b>	<b>User management</b> <b>Navigation: Home &gt; Settings &gt; User management</b> <b>See User Management (page 46)</b>
	<b>System and data management</b> <b>Navigation: Home &gt; Settings &gt; System and data management</b> <b>See System- and Data Management (page 50)</b>
	<b>Deleting results</b> <b>See Graphical Evaluations of Measurement Results (page 85)</b>

#### Note

- If password protection is mandatory requirement, the access right **User Preference settings** must be disabled.
- If a user does not have the appropriate access rights, the respective navigation elements are not shown (on Home screen) or are disabled (greyed out).

## 6.5.2 Users

**Navigation:** Home > Settings > User management > Users

In this menu you can create, edit, or delete user accounts.

### Attention

#### Important note for the Administrator password.

We recommend that you note down your administrator password and keep it in a safe place. If you forgot the password for the default administrator access, it is not possible to regain access to the moisture analyzer. In this case contact your METTLER TOLEDO representative.

### Creating a new user account

#### Note

The user account name must be unique.

- ▶ Menu **Users** selected.
- 1 Tap [**New...**].
- 2 Enter the name of the new user account and confirm with [**OK**].
- 3 Edit the properties of the new user account.

### Editing an existing user account

- ▶ Menu **Users** selected.

- 1 Select the user account you wish to edit.
- 2 Select menu **User properties**.
- 3 Edit the user account parameters.
- 4 To store the settings, tap [**Save**].

You can define the following parameters:

Parameter	Explanation	Values
<b>User name</b>	Name of the user account. Name should be unique and unambiguous.	<b>any</b>
<b>Full name</b>	Full name of the user (optional).	<b>any</b>
<b>Description</b>	Descriptive text for the user account (optional).	<b>any</b>
<b>Account active</b>	Activate or deactivate the user account. Inactive user accounts are not available for login.	<input type="checkbox"/> (deactivated)*   <input checked="" type="checkbox"/> (activated)
<b>Password</b>	Create a new or change an existing password. <b>OFF</b> = no password protection.	<b>OFF*</b>   <b>ON</b>   <b>any</b>
<b>Group</b>	Assign the user account to a particular group.	<b>available groups</b>

\* Factory setting

#### Note

- To view the date and time of last modification made to a user account, select the respective account and tap [**History**].
- If password protection is mandatory requirement, the access right **User Preference settings** must be disabled, see Groups (page 46).

### Deleting a user account

- ▶ Menu **Users** selected.

- 1 Select the user account you wish to delete.
- 2 Tap [**Delete**]. Confirm the message box.

#### Note

You cannot delete the Administrator account or the account that is currently active.

### 6.5.3 Account Policies

**Navigation:** Home > Settings > User management > Account policies

In this menu you can set the default startup user.

You can define the following parameters:

Parameter	Explanation	Values
<b>Default startup user</b>	Select the default user account for login at startup.	<b>OFF   ON*   available user accounts</b>

\* Factory setting

**Note**

If a non-standard user logs out, the default startup user profile is automatically activated.

## 6.6 System- and Data Management

**Navigation:** Home > Settings > System and data management

This menu item allows you to export or import settings and methods to or from an external USB storage device, as well as to restore the system (depending on the user rights).

### Menu structure

Main menu	Submenu	Further information
Export / Import	Export settings and methods to external storage devices...	see Export / Import (page 50)
	Import settings and methods from external storage device...	
Back up / Restore	Back up your system on external storage device...	see Back up / Restore (page 51)
	Restore your system from selected back up...	
Reset	no submenu	see Reset (page 52)
Update	Update your instrument software	see Update (page 52)

#### Note for using USB memory sticks

- Memory sticks up to 32 GB are supported.
- Recommended formatting: FAT32 (NTFS not supported).
- Max. cluster size: 32 KB.
- Max. file size: 32 MB.
- Make sure that the stick is fully inserted.
- Make sure that the write protection is deactivated if present.

### 6.6.1 Export / Import

**Navigation:** Home > Settings > System and data management > Export / Import

This menu item allows you to export or import settings and methods to or from an external storage device. These data can be transferred to other instruments of the same type and can be useful to configure multiple instruments with the same specifications.

#### Note

- Software Version must be equal or higher.
- Data transfer from HX models to HS models is limited. Features which are not supported by HS models cannot be imported, e.g. Step drying or high resolution.
- Export / import of methods can also be performed from the menu **Method Definition**.

#### Export settings and methods to external storage devices...

You can define the following parameters:

Parameter	Explanation	Values
File name	Defines the name of the new data file.	any
Location	Finds the location on the storage device.	Browse and select
Export selection	Defines the data for export.  Note <ul style="list-style-type: none"><li>• <b>User management and user preferences</b> contains: User management settings, user preferences</li><li>• <b>System, application and QM settings</b> contains: System settings, application settings, quality management settings</li></ul>	All*   <input checked="" type="checkbox"/> User management and user preferences   <input checked="" type="checkbox"/> System, application and QM settings   <input checked="" type="checkbox"/> Methods

- \* Factory setting
- An external storage device is connected e.g. memory stick.
- Settings are made.
- To start, tap [**Export**].  
To abort, tap [**Cancel**].

#### **Import settings and methods from external storage device...**

You can define the following parameters:

Parameter	Explanation	Values
<b>Import from file</b>	Defines the data to be imported.	<b>Browse and select</b>
<b>Location</b>	Shows the location of the import file.	—
<b>Import selection</b>	Defines the data for import.	All*   <input checked="" type="checkbox"/> User management and user preferences   <input checked="" type="checkbox"/> System, application and QM settings   <input checked="" type="checkbox"/> Methods

- \* Factory setting
- Import settings and methods from external storage devices – is selected.
- An external storage device is connected e.g. memory stick.

- 1 Tap **Browse and select**

⇒ **Import from file** appears.

- 2 Select Device and import file.

⇒ Full menu of Import settings and methods from external storage devices appears.

- 3 Tap Import selection and select the data for import if needed.

- 4 To start, tap Import button and follow the instructions in the message window.  
To abort, tap [**Cancel**].

## **6.6.2 Back up / Restore**

### **Navigation: Home > Settings > System and data management > Back up / Restore**

This menu item allows you to create a recovery point of the system and to store them on an external storage device. We advise you to create a recovery point of the system regularly. So you are able to restore the system with all data in fault.

#### **Attention**

- After restoring, the system is in backup status. That means, that newer data such as settings, methods or results are lost.
- Restore is only possible on the same instrument as the back up was carried out.

#### **Backup**

You can define the following parameters:

Parameter	Explanation	Values
<b>File name</b>	Defines the name of the new data file.	<b>any</b>
<b>Location</b>	Finds the location on the storage device.	<b>Browse and select</b>

Procedure:

- An external storage device is connected e.g. memory stick.
- **Back up your system on external storage device...** – is selected.

- 1 Define the name of the new data file.

- 2 Define the location on the storage device.
- 3 To confirm, tap [OK].
- 4 To start, tap [Backup].  
To abort, tap [Cancel].

### **Restore**

You can define the following parameters:

Parameter	Explanation	Values
<b>Restore from file</b>	Finds the location on the storage device and selects the file for restoring.	<b>Browse and select</b>

Procedure:

- **Restore your system from selected back up...** – is selected.
  - An external storage device is connected e.g. memory stick.
- 1 Tap **Restore from file...** (**Browse and select**).
    - ⇒ Storage device appears.
  - 2 Select the file for restoring.
  - 3 To start, tap [Restore].  
To abort, tap [Cancel].
    - ⇒ Confirmation window appears.
  - 4 Confirm with [Restore].
    - ⇒ The system will restore the data and then perform a restart. Wait until the system has completely started up again.

### **6.6.3 Reset**

**Navigation:** Home > Settings > System and data management > Reset

This menu item allows you to reset the Instrument to factory settings. Date, time, weight and temperature adjustments/history are not affected.

---

#### **CAUTION**



#### **Data loss after system reset.**

After resetting, the instrument is in state as delivered. That means, that all data such as settings, methods or results are lost.

- We recommend you, first save the appropriate data on an external storage device, **see Export / Import (page 50)** and **Back up / Restore (page 51)**.

You can define the following parameters:

Parameter	Explanation	Values
<b>Reset</b>	Resets the instrument to factory settings.	<b>none</b>

### **6.6.4 Update**

**Navigation:** Home > Settings > System and data management > Update

#### **Note**

This function is not available with approved instruments. For update, contact your METTLER TOLEDO representative.

METTLER TOLEDO is continuously improving its instrument firmware (software) for the benefit of customers. So that the customer can benefit quickly and easily from further developments, METTLER TOLEDO makes the latest

firmware versions available on the Internet. The firmware made available on the Internet has been developed and tested by Mettler-Toledo AG using processes that meet the guidelines of ISO 9001. Mettler-Toledo AG does not, however, accept liability for consequences that might arise from using the firmware.

## Operating Principle

If you register on the following METTLER TOLEDO website, you will find all relevant information and updates for your instrument:

[www.mettler-toledo-support.com](http://www.mettler-toledo-support.com)

## Update Procedure

### CAUTION



#### Data loss after system update.

During update of the system, the existing data such as settings, methods or results are migrated. It may happen that data are lost or the update fails.

- We advise you, first create a recovery point of the system on an external storage device, **see Back up / Restore (page 51)**.

For each software update, the following steps must be performed:

**Step 1** Backup system data.

**See Back up / Restore (page 51), procedure **Backup**.**

**Step 2** Execute software update (see below).

**Step 3** Restore system data if needed.

**See Back up / Restore (page 51), procedure **Restore**.**

### Execute software update

This menu item allows you to update the Instrument.

You can define the following parameters:

Parameter	Explanation	Values
<b>Update from file</b>	Finds the location on the storage device and selects the file for updating.	<b>Browse and select</b>

- Back up of the system data is already performed.
- 1 Insert USB stick with software for update.
- 2 Select **Home > Settings > System and data management > Update**.  
⇒ **Update** screen appears.
- 3 Tap **Update from file**. **Browse and select** the software update package file on the USB stick.
- 4 Tap **[Update]**  
⇒ Screen Confirm Software Update appears.
- 5 Read the Information on the screen.
  - If an update is needed, tap **[Update]**.
  - If the software is up-to-date, tap **[OK]**.
- 6 Wait until the software update is completely finished, i.e. the system returned to the home screen (the instrument might reboot up to twice in between).

### Attention

Do not remove the USB stick before the instrument has completely restarted.

**Also see**

- Touch Screen Adjustment (page 38)

## 7 Test/Adjust

**Navigation:** Home > Test/Adjust

This function offers you to adjust or test the integrated balance and the heating module. For the relevant settings see Test / Adjustment settings (page 42).

### Menu structure

Main menu	Submenu	Further information
<b>Adjustments</b>	<b>Weight adjustment - internal</b>	<b>see Weight Adjustment - Internal (page 56)</b>
	<b>Weight adjustment - external</b>	<b>see Weight Adjustment - External (page 56)</b>
	<b>Temperature adjustment</b>	<b>see Temperature Adjustment (page 57)</b>
	<b>Adjustment Printouts</b>	<b>see Adjustment Printout Examples (page 59)</b>
<b>Tests</b>	<b>Weight test - internal</b>	<b>see Weight test - internal (page 60)</b>
	<b>Weight test - external</b>	<b>see Weight test - external (page 60)</b>
	<b>Temperature test</b>	<b>see Temperature test (page 61)</b>
	<b>Test Printouts</b>	<b>see Test Printout Examples (page 62)</b>
<b>History</b>	no submenu	<b>see History (page 63)</b>

### 7.1 Adjustments

**Navigation:** Home > Test/Adjust > Adjustments

In this menu item you can adjust the balance as well as the heating module of your instrument. For relevant settings see Test / Adjustment settings (page 42).

#### Attention

- To obtain accurate results, the balance must be adjusted at the point of use under measuring condition in order to match the gravitational acceleration at its location. The instrument must be connected to the power supply for approximately 60 minutes in order to reach operating temperature before adjusting. Adjusting is necessary:
  - before the instrument is used for the first time.
  - after a change of location.
- We advice you to wait at least 30 minutes after a drying operation (or previous heating module adjustment) before performing the adjustment.

#### Fully automatic adjustment FACT

This instrument is equipped with fully automatic adjustment with two internal weights called Fully Automatic Calibration Technology (**FACT**).

The balance adjusts itself automatically:

- after the warm-up phase after connection to the power supply.
- when a change in the ambient conditions (temperature) could lead to a noticeable deviation in the measurement.
- on a fixed time interval

FACT is activated by default and can be switched off as required e.g. when performing an external adjustment, see FACT (Fully automatic adjustment) (page 45).

**Navigation:** Home > Settings > Quality management > Test / Adjustment settings > FACT

#### Note

With approved models **FACT** cannot be switched off.

### 7.1.1 Weight Adjustment - Internal

**Navigation:** Home > Test/Adjust > Adjustments > Weight adjustment - internal

This function allows you to adjust the balance with the built-in weights. The internal adjustment is equivalent to the FACT adjustment.

Perform this function as follows:

- 1 Tap the menu item **Weight adjustment - internal**.  
⇒ The adjustment screen appears.
- 2 Clear pan and tap [**Start adjustment**].  
⇒ The balance adjusts itself automatically.
- ⇒ The instrument indicates when the adjustment process is done. The balance is adjusted and ready to use for further measurements. The display shows the adjustment results. The results can be printed out by tapping [].

### 7.1.2 Weight Adjustment - External

**Navigation:** Home > Test/Adjust > Adjustments > Weight adjustment - external

This function allows you to adjust the balance using an external weight. We recommend to use certified weights so that full traceability is guaranteed.

#### Note

We recommend you to disable FACT. Otherwise FACT overwrites the adjustment.

Perform this function as follows:

- FACT is off.
  - Test weight and Adjustment settings are defined.  
**see** Test / Adjustment settings (page 42)
- 1 Have required test weight ready.
  - 2 Tap the item **Weight adjustment - external**.  
⇒ The adjustment screen appears.
  - 3 Clear sample pan holder and tap [**Start adjustment**].
- Note**
- We recommend not to use a pan.
- ⇒ The required value flashes and prompts you to load the weight, e.g. "100.00 g".
- 4 Load the required test weight in the center of sample pan holder.  
⇒ The balance indicates the adjustment process, "\_\_\_\_\_ appears.
  - 5 When the display flashes "**000.00**" remove the test weight.
  - ⇒ The balance is adjusted and ready to use for further measurements. The display shows the adjustment results. The results can be printed out by tapping []

#### Note

- After a timeout the error message appears **Weight out of range. The adjustment has been aborted**. The adjustment was not executed.
  - 1 Confirm with [**OK**].
  - 2 Remove the test weight for unloading.
  - 3 Repeat the adjustment.

### 7.1.3 Temperature Adjustment

**Navigation:** Home > Test/Adjust > Adjustments > Temperature adjustment

This function allows you to adjust the temperature control of the heating module. You need the optional **Temperature kit** for performing this function, **see** Accessories and Spare Parts (page 105). To learn when an adjustment of the heating module is necessary, **see** Notes on Adjustment of Balance and Heating Module (page 109). We advise you to wait at least 30 minutes after a drying operation (or previous heating module adjustment) before performing the adjustment.

#### Note

- The duration of the temperature adjustment is 30 minutes. (15 minutes for each measuring temperature).
- The sample chamber must be less than 50 °C before a further adjustment or test can be done.
- It is also possible to perform a test first, and then to transform the test into an adjustment if required. Only possible for tests conducted with 2 temperatures, **see** Temperature test (page 61).
- For temperature adjustment settings **see** Adjustment Settings (page 44).

---

#### CAUTION



#### Danger of burns


Sample chamber may still be hot.

- Cool down instrument before setting up.


- 
- ▶ Adjustment settings are defined, **see** Adjustment Settings (page 44).
  - Tap menu item **Temperature adjustment**.  
⇒ Work screen **Temperature adjustment** appears.

#### Setting up Drying Unit

- ▶ Have required **Temperature kit** ready.
  - ▶ Instrument is on
  - ▶ Sample chamber is open.
  - ▶ Instrument is cooled down.
- 1 Remove sample pan handler (with pan) (1).
  - 2 Remove sample pan holder (2).
  - 3 Contact areas (3) should be clean. Clean them if needed.



- Insert **Temperature kit** (4).



### Start adjustment

- **Temperature kit** is inserted.

- 1 Tap [**Start adjustment**].

#### Note

The adjustment process takes 30 minutes.

- ⇒ The instrument starts the adjustment process. The screen shows the current temperature and the remaining time.
- ⇒ The instrument heats up to the target temperature 1 for determining the predefined lower temperature.
- ⇒ After 15 minutes, the instrument adjusts the lower temperature and continues with the process.
- ⇒ The instrument heats up to the target temperature 2 for determining the predefined upper temperature.
- ⇒ After 15 minutes, the instrument adjusts the upper temperature and concludes the adjustment.

- 2 • To print out the results, tap [print].
  - To display or print out the results of previous adjustments, tap [**History**].
  - To return to the home screen, tap [home].

- 3 After cooling down, remove **Temperature kit** and set up drying unit for measurement.

**See** History (page 63) and Setting up Drying Unit (page 26)

#### Note

Your calibrated temperature adjustment kit can be re-calibrated. Please contact your local METTLER TOLEDO representative for more information.

## 7.1.4 Adjustment Printout Examples

### Weight adjustment internal      Weight adjustment external      Temperature adjustment

-WEIGHT ADJUST INTERNAL-

14.10.2011 11:51

METTLER TOLEDO  
Halogen MoistureAnalyzer

Type HX204  
SNR(Drying Unit) 2345  
SNR(Terminal) 6788  
SW(Drying Unit) 0.60.09  
SW(Terminal) 4.20628

User name Administrator

Cell temperature 24.60 °C  
Drying Unit leveled  
Adjustment done

Signature  
.....

----- END -----

-WEIGHT ADJUST EXTERNAL-

14.10.2011 11:51

METTLER TOLEDO  
Halogen MoistureAnalyzer

Type HX204  
SNR(Drying Unit) 2345  
SNR(Terminal) 6788  
SW(Drying Unit) 0.60.09  
SW(Terminal) 4.20628

User name Administrator

Weight ID ECW-100/1  
Nominal Weight 100.000 g  
Cell temperature 25.20 °C  
Drying Unit leveled  
Adjustment done

Signature  
.....

----- END -----

-TEMPERATURE ADJUSTMENT-

14.10.2011 11:51

METTLER TOLEDO  
Halogen MoistureAnalyzer

Type HX204  
SNR(Drying Unit) 2345  
SNR(Terminal) 6788  
SW(Drying Unit) 0.60.09  
SW(Terminal) 4.20628

User name Administrator

Temp Kit ID MT-414/A  
Temp1 target 100 °C  
Temp1 actual 97 °C  
Temp2 target 160 °C  
Temp2 actual 162 °C  
Adjustment done

Signature  
.....

----- END -----

## 7.2 Tests

### Navigation: Home > Test/Adjust > Tests

In this menu item you can check the adjustment of the balance as well the temperature of the heating module. For relevant settings see Test / Adjustment settings (page 42).

#### 7.2.1 Weight test - internal

##### Navigation: Home > Test/Adjust > Tests > Weight test - internal

This function allows you to test the balance with the built-in weight. Perform this function as follows:

- ▶ Test settings are defined (Factory setting of the tolerance is 0.0010 %)  
see Test / Adjustment settings (page 42)
- 1 Open sample chamber
- 2 Tap the item **Weight test - internal**.  
⇒ The test screen appears.
- 3 Clear pan and tap [**Start test**].  
⇒ The balance is tested automatically.
- ⇒ When the test process is done, the display shows the test results and indicates whether the test is passed or failed according to defined tolerances.

The test results can be printed out by tapping [print].

#### 7.2.2 Weight test - external

##### Navigation: Home > Test/Adjust > Tests > Weight test - external

This function allows you to test the balance using an external weight. Perform this function as follows:

- ▶ Test weight and test settings are defined.  
see Test / Adjustment settings (page 42)
- 1 Have required test weight ready.
- 2 Open sample chamber.
- 3 Tap the item **Weight test - external**.  
⇒ The test screen appears.
- 4 Clear sample pan holder and tap [**Start test**].

##### Note

We recommend not to use a pan.

- ⇒ The required value flashes and prompts you to load the weight.
- 5 Load the required test weight.  
⇒ The balance indicates the test process, "\_\_\_\_\_" appears.
- 6 When the display flashes "**000.00**" remove the test weight.
- ⇒ When the test process is done, the display shows the test results and indicates whether the test is passed or failed according to defined tolerances. The results can be printed out by tapping [print].

##### Timeout

- ▶ After a timeout of 75 seconds the error message appears **Weight out of range. The test has been aborted.**  
The test was not executed.
- 1 Confirm with [**OK**].
- 2 Repeat the test.

### 7.2.3 Temperature test

**Navigation:** Home > Test/Adjust > Tests > Temperature test

This function allows you to test the temperature control of the heating module. You need the optional Temperature Kit for performing this function, **see** Accessories and Spare Parts (page 105). To learn when an test of the heating module is necessary, **see** Notes on Adjustment of Balance and Heating Module (page 109). We advise you to wait at least 30 minutes after a drying operation (or previous heating module adjustment) before performing a test.

#### Note

- The duration of the temperature test is 15 minutes for each measuring temperature.
- The sample chamber must be cooled down below 50 °C before a further adjustment or test can be done.
- It is possible to perform a test and then subsequently to transform the test into an adjustment if required. This is only possible for tests conducted with temperatures 1 and 2.
- Temperature test settings **see** Test Settings (page 43).

#### Setting up the Drying Unit for temperature test

Same procedure as for temperature adjustment, **see** Temperature Adjustment (page 57).

---

#### CAUTION



#### Danger of burns

Sample chamber may still be hot.

- Cool down instrument before setting up.

---

#### Performing temperature test

- ▶ Test settings are defined, **see** Test Settings (page 43).
  - ▶ Setting up the drying unit for temperature testing has been carried out.
- 1 Tap menu item **Temperature test**.  
⇒ Work screen **Temperature test** appears.
  - 2 Tap [**Start test**].  
**Note**  
The testing process takes 15 minutes for each temperature (depending on the settings).  
⇒ The instrument starts the testing process. The screen shows the current temperature and remaining time.  
⇒ The instrument is heating up to the target temperature 1 for determining the predefined lower temperature.  
⇒ After 15 minutes, the instrument displays and stores the measured lower temperature and continues with the process.  
⇒ The instrument is heating up to the target temperature 2 for determining the predefined upper temperature.  
⇒ After 15 minutes, the instrument displays and stores the measured upper temperature.  
⇒ If temperature 3 is defined, the procedure has an additional step.  
⇒ The test is done and indicates whether the test has passed or failed according to defined tolerances.
  - 3 Decide if an adjustment is needed.
  - 4 • To return to the menu **Tests**, tap [**Tests**].
    - To print out the results, tap [].
    - To display or print the results at any time, tap [**History**].
    - To return to the home screen, press [].
  - 5 After cooling down, remove temperature adjustment kit and set up drying unit for measurement, **see** Setting up Drying Unit (page 26).

## 7.2.4 Test Printout Examples

### Weight test internal

```
--WEIGHT TEST INTERNAL--
14.10.2011    11:51
METTLER TOLEDO
Halogen MoistureAnalyzer

Type          HX204
SNR(Drying Unit) 2345
SNR(Terminal)   6788
SW(Drying Unit) 0.60.09
SW(Terminal)     4.20628

User name    Administrator

Target       100.000 %
Actual        99.999 %
Difference    -0.001 %
Cell temperature      24.30 °C
Drying Unit    leveled
Test          passed

Signature
.....
----- END -----
```

### Weight test external

```
--WEIGHT TEST EXTERNAL--
14.10.2011    11:51
METTLER TOLEDO
Halogen MoistureAnalyzer

Type          HX204
SNR(Drying Unit) 2345
SNR(Terminal)   6788
SW(Drying Unit) 0.60.09
SW(Terminal)     4.20628

User name    Administrator

Weight ID      ECW-100/1
Nominal Weight 100.000 g
Actual        100.001 g
Difference     0.001 g
Tolerance      +/- 0.002 g
Cell temperature      23.83 °C
Drying Unit    leveled
Test          passed

Signature
.....
----- END -----
```

### Temperature test

```
----TEMPERATURE TEST----
14.10.2011    11:51
METTLER TOLEDO
Halogen MoistureAnalyzer

Type          HX204
SNR(Drying Unit) 2345
SNR(Terminal)   6788
SW(Drying Unit) 0.60.09
SW(Terminal)     4.20628

User name    Administrator

Temp Kit ID    MT-414/A
Temp1 target    100 °C
Temp1 actual     99 °C
Temp1 tolerance  +/- 2 °C
Temp2 target    160 °C
Temp2 actual     159 °C
Temp2 tolerance  +/- 2 °C
Test          passed

Signature
.....
----- END -----
```

## 7.3 History

**Navigation:** Home > Test/Adjust > History

The instrument always records all test or adjustment operations that have been made and saves them in a memory which is specially protected against power failure (limited to the last 50 records per history selection).

### Note

Aborted adjustments or tests will not be saved.

When the History is selected, a list appears with the history selection as follows:

- **Weight test history**
- **Weight adjustment history**
- **Temperature test history**
- **Temperature adjustment history**

The following information is displayed:

#### Weight test history

Weight test external		Weight test internal	
Calibration weight identification		Nominal weight	100 %
Nominal weight	g	Actual weight	%
Actual weight	g	Difference	%
Difference	g	Tolerance	%
Tolerance	g	Temperature	°C
Temperature	°C	Leveling information	
Leveling information			

#### Weight adjustments history

Weight adjustment external		Weight adjustment internal	
Calibration weight name		Temperature	°C
Calibration weight identification		Leveling information	
Nominal weight	g		
Temperature	°C		
Leveling information			

#### Temperature adjustment/test history

Temperature adjustment		Temperature test	
Adjustment kit identification		Adjustment kit identification	
Temperature 1	target - actual	Temperature 1	target - actual
Temperature 2	target - actual	Temperature 2	target - actual
		Free temperature	target - actual
		Tolerances for each temperature	°C

The selected individual results can be printed out by tapping [  ].

## 8 Method Definition

Navigation: Home > Method definition

### What is a method?

Methods simplify and accelerate your daily work. A method contains all settings for measuring the moisture content of a particular sample (substance). It can be recalled by tapping a measurement button or a shortcut and your instrument immediately operates with the corresponding settings.

The **optimal setting of parameters and the drying time** depends on the type and size of the sample and the desired accuracy of the measurement result. The exact parameters can only be determined experimentally, **see** How to Obtain Best Results (page 109). Your Instrument helps you to determine the settings.

### Method definition

This function offers you to define new methods and to change, delete, export or import existing methods depending on the user rights. It allows you to store up to 300 individual methods.

All parameters using in a drying method, can be defined under this menu item.

### Note

- In most cases it is sufficient to set **Main measurement parameters**.
- You will find more information about defining methods in the delivered application brochure «Guide to Moisture Analysis» or **see** How to Obtain Best Results (page 109).

### Prerequisite

The parameter menu appears only if a method already exists and is selected in the method definition dialog or create a new method.

### Menu structure

Main menu	Submenu	Further information
<b>Main measurement parameters</b>	<b>Drying program</b> (including temperature and switch-off criteria)	<b>see</b> Settings of Drying Program (page 66)
	<b>Display mode</b>	<b>see</b> Settings of Display Mode (page 72)
	<b>Start weight</b>	<b>see</b> Settings of Start Weight (page 74)
<b>Result and value handling</b>	<b>Control limits</b>	<b>see</b> Control limits (page 75)
	<b>Resolution</b>	<b>see</b> Resolution (page 76)
<b>Workflow handling</b>	<b>Starting mode</b>	<b>see</b> Starting Mode (page 77)
	<b>Preheating</b>	<b>see</b> Preheating (page 77).
<b>General method properties</b>	<b>Method name</b>	<b>see</b> Method name (page 79)

## **Defining a new Method**

### **Note**

A method name can only exist once.

- **Method definition** is selected.

- 1 Tap [**New...**].  
⇒ The keypad appears.
- 2 Enter a name for the new method. Name should be unique and unambiguous. 1 to 30 characters are possible (including spaces).
- 3 Confirm with [**OK**].  
⇒ The parameter menu for the new method appears.
- 4 Set the desired parameters e.g. **Main measurement parameters**.
- 5 To store the method, tap [**Save**].

## **Editing an existing method**

- **Method definition** is selected.

- 1 Tap the method in the list you want to edit.  
⇒ The parameter menu for the selected method appears.
- 2 Edit the desired parameters e.g. **Main measurement parameters**.
- 3 To store the method, tap [**Save**].

## **Copying an existing method**

- **Method definition** is selected.

- 1 Tap the method in the list you want to copy.  
⇒ The parameter menu of the desired method appears.
- 2 Tap [**Save as...**].  
⇒ The keypad appears.
- 3 Enter a new name for the copied method. Name should be unique and unambiguous. 1 to 30 characters are possible.
- 4 To store the method, tap [**Save**].

## **Removing an existing method**

### **Note**

All results of this method are also removed.

- **Method definition** is selected.

- 1 Tap the method in the list you want to remove.  
⇒ The parameter menu of the desired method appears.
- 2 Tap [**Delete**].  
⇒ A message box appears.
- 3 Confirm with [**Delete**].  
⇒ The desired method is removed.

### **Note**

A possible shortcut to this method is not removed.

For removing shortcuts **see** Using Shortcuts (page 83)

## 8.1 Main Measuring Parameters

**Navigation:** Home > Method Definition > Method name > Main measurement parameters

These parameters are relevant for measuring and must be determined for all samples. Most samples can be determined with these parameters.

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Drying program</b>	Defines the drying program which is best suited for the specific sample. (including temperature and switch-off criteria)	<b>see</b> Setting the Drying Program (page 66)
<b>Display mode</b>	Defines the type of value for displaying and printing.	<b>see</b> Settings of Display Mode (page 72)
<b>Start weight</b>	Defines a start weight so that the samples always have approximately the same weight .	<b>see</b> Settings of Start Weight (page 74)

### 8.1.1 Settings of Drying Program

**Navigation:** Home > Method Definition > Method name > Main measurement parameters > Drying program

This function offers you different predefined drying programs for optimum matching of the drying characteristics to the sample used. Furthermore, the drying temperature, switch-off criterion as well as the start weight can be set. Carry out a test measurement for determining the appropriate switch-off criterion, if you do not know the behavior of the sample. For carry out a test measurement **see** Test a Method (page 80).

#### Note

You will find more information about defining methods in the delivered application brochure «Guide to Moisture Analysis».

You can define the following parameters:

Parameter	Explanation	Values
<b>Drying program</b>	Defines the drying program which is best suited for the specific sample.	<b>Standard*</b>   <b>Rapid</b>   <b>Gentle</b>   <b>Steps</b>

\* Factory setting

Further information:

- **Standard** drying **see** Settings of Standard drying (page 66)
- **Rapid** drying **see** Settings of Rapid drying (page 67)
- **Gentle** drying **see** Settings of Gentle drying (page 68)
- **Steps** drying **see** Settings of Step drying (page 69)

#### 8.1.1.1 Settings of Standard drying



##### Standard drying

This drying program is set in the factory and is suitable for most samples. The sample is heated to the drying temperature.

##### Factory setting

**Drying temperature** = 105 °C, **Switch-off criterion** 3 = 1 mg / 50 s

You can define the following parameters:

Parameter	Explanation	Values
<b>Drying temperature</b>	Defines the drying temperature.	40...230 °C
<b>Switch-off criterion</b>	Defines the criterion when the instrument should end the drying.	1 (1 mg / 10 s)   2 (1 mg / 20 s)   3 (1 mg / 50 s)*   4 (1 mg / 90 s)   5 (1 mg / 140 s)   Timed...   Free (mg / s)...   Free (% / s)...


### Setting the Drying Temperature

**Navigation:** Method Definition > Name of method > Main measurement parameters > Drying temperature

In this menu item you can set the final drying temperature.

**Note:**

The admissible input range for the drying temperature is indicated.



### Setting Switch-off criterion

see Settings of Switch-off Criterion (SOC) (page 70)

#### 8.1.1.2 Settings of Rapid drying



##### Rapid drying

This drying program is primarily suitable for samples with a moisture content over 30%. Following the start, the selected temperature is exceeded by 40% for 3 minutes (however, is possible up to maximum 230°C) to compensate for the cooling due to vaporization and accelerate the drying process. The drying temperature is then lowered to the set value and maintained.

##### Factory setting

Drying temperature = 105 °C, Switch-off criterion 3 = 1 mg / 50 s

You can define the following parameters:

Parameter	Explanation	Values
<b>Drying temperature</b>	Defines the drying temperature.	40...230 °C
<b>Switch-off criterion</b>	Defines the criterion when the instrument should end the drying.	1 (1 mg / 10 s)   2 (1 mg / 20 s)   3 (1 mg / 50 s)*   4 (1 mg / 90 s)   5 (1 mg / 140 s)   Timed...   Free (mg / s)...   Free (% / s)...

\* Factory setting


## Setting the Drying Temperature

Navigation: Method Definition > Name of method > Main measurement parameters > Drying temperature

In this menu item you can set the final drying temperature.

### Note:

The admissible input range for the drying temperature is indicated.



- 1 Start of drying  
2 Final temperature

## Setting Switch-off criterion

see Settings of Switch-off Criterion (SOC) (page 70)

### 8.1.1.3 Settings of Gentle drying



#### Gentle drying

This drying program is suitable for the gentle drying of **substances which tend to form a skin** (e.g. substances containing sugar or volatile substances). With this program the temperature is continuously increased and attains the selected drying temperature **only after the elapse** of the so-called ramp time. The «ramp», i.e. the time that should elapse between the start of drying and attainment of the final temperature can be pre-set.

#### Factory setting

Drying temperature = 105 °C, Ramp time = 3:00 min,  
Switch-off criterion 3 = 1 mg / 50 s

You can define the following parameters:


Parameter	Explanation	Values
Drying temperature	Defines the drying temperature.	40...230 °C
Ramp time	Defines the time in minutes that should elapse between the start of drying and attainment of the final temperature for <b>Gentle</b> drying.	0...480 min
Switch-off criterion	Defines the criterion when the instrument should end the drying.	1 (1 mg / 10 s)   2 (1 mg / 20 s)   3 (1 mg / 50 s)*   4 (1 mg / 90 s)   5 (1 mg / 140 s)   Timed...   Free (mg / s)...   Free (% / s)...

\* Factory setting

## Setting the Drying Temperature

Navigation: Method Definition > Method name > Main measurement parameters > Drying program GentleDrying temperature

In this menu item you can set the desire final drying temperature.




- 1 Start of drying  
2 Final temperature

### Setting the ramp time

**Navigation:** Method Definition > Method name > Main measurement parameters > Drying program Gentle > Ramp time

In this menu item you can define the **Ramp time**, i.e. the time that should elapse between the start of drying and attainment of the final temperature. The ramp is started once the temperature reaches 50 °C.



### Setting Switch-off criterion

see Settings of Switch-off Criterion (SOC) (page 70)

#### 8.1.1.4 Settings of Step drying



##### Step drying

This drying program is suitable for the drying of substances composed of several components which vaporize at different temperatures (e.g. ethereal oils). With this program drying is performed stepwise, i.e. the sample is preheated to a particular temperature (1st step) and kept at this temperature for the selected switch-off criterion e.g. time or weight loss per unit of time. The temperature can be increased for the next step, lowered or remain the same. At the last step, the switch-off criterion terminates the measurement. Maximum 5 steps are selectable.

Step drying can also be used for faster determining of samples with high moisture content. In this case the first step should be set with a higher temperature than for the last step. This reduces evaporation.

Tip for the measurement of plastic granules:

Setting of switch-off criterion "timed" for the first step (possibly same temperature setting as for step 2). The larger sample (e.g. 30 g) has to be heated first before it gives off the small amount of moisture. This prevents that the measurement is terminated prematurely. Setting of switch-off criterion "5" for the second step which terminates the measurement automatically.

##### Factory setting

Step 1, **Temperature** = 50 °C, **Switch-off criterion** = 5:00 min

Step 2, **Temperature** = 105 °C, **Switch-off criterion** 3 = 1 mg / 50 s


You can define the following parameters:

Parameter	Explanation	Values
<b>Drying steps</b>	Defines the number of steps for Step drying. This dialog includes the setting of temperature and switch-off criterion for each step.	1...5 Steps
<b>Temperature</b>	Defines the drying temperature for each Step.	50...230 °C
<b>Switch-off criterion</b>	Defines the criterion when the instrument should end the drying or should start the next step.	1 (1 mg / 10 s)   2 (1 mg / 20 s)   3 (1 mg / 50 s)*   4 (1 mg / 90 s)   5 (1 mg / 140 s)   Timed...   Free (mg / s)...   Free (% / s)...

\* Factory setting

## Drying steps

Navigation: Method Definition > Method name > Main measurement parameters > Drying programSteps > Drying steps



- 1 Start of drying
- 2 Step temperature
- 3 Next step, **Switch-off criterion**
- 4 Last step

### Setting Switch-off criterion

see Settings of Switch-off Criterion (SOC) (page 70)

#### 8.1.1.5 Settings of Switch-off Criterion (SOC)

Navigation: Home > Method Definition > Method name > Main measurement parameters > Drying program

This function offers you different switch-off criteria. A switch-off criterion defines when the instrument should end the drying or should start the next step ("Step drying"). Switch-off criteria ensure that measurements are finished in the same condition (weight loss per time) every time, ensuring repeatable measurements.

##### Note

Accurate results require same start weights, see Settings of Start Weight (page 74).

You can define the following parameters:

Parameter	Explanation	Values
Switch-off criterion	Defines the criterion when the instrument should end the drying.	<b>1 (1 mg / 10 s)</b>   <b>2 (1 mg / 20 s)</b>   <b>3 (1 mg / 50 s)*</b>   <b>4 (1 mg / 90 s)</b>   <b>5 (1 mg / 140 s)</b>   Timed...   Free (mg / s)...   Free (% / s)...

\* Factory setting

- Weight loss per unit of time (5 preprogrammed settings)
- Free switch-off criterion (2 different settings)
- Timed switch-off

### Weight loss per unit of time

This switch-off is based on a weight loss per unit of time. As soon as the mean weight loss is less than a preset value during a specified time, the instrument considers drying as complete and automatically discontinues the measurement process.

##### Note


The switch-off criterion is inactive during the first 30 sec.

### The following 5 preprogrammed settings are available

Switch-off criterion	$\Delta g$	$\Delta t$	Description
<b>1</b>	1 mg	10 s	This setting is suitable for fast measurements to determine a trend.
<b>2</b>	1 mg	20 s	This setting is suitable for quick drying samples.
<b>3</b>	1 mg	50 s	This is the <b>factory setting</b> . It is suitable for most kind of samples.
<b>4</b>	1 mg	90 s	This setting is suitable for samples which dry moderately quickly or for samples with higher accuracy requirements.

Switch-off criterion	$\Delta g$	$\Delta t$	Description
5	1 mg	140 s	This setting is suitable for samples which dry very slowly (trapped moisture, skin formation) or for samples with very low moisture content e.g. plastics. Not suitable for very temperature sensitive samples.

The graph below exemplifies the mode of operation of the switch-off operation (not to scale).



$t$  = time

$W$  = weight of sample

1, 3, 5 = switch-off criteria shown as an example

1) = equal area

2) = mean weight loss per unit of time

### Free switch-off criterion

The free switch-off criterion is based on a user-defined mean weight loss per unit of time.

The following 2 settings are available:

- **Switch-off criterion > Free (mg / s)...** (weight loss per unit of time)
- **Switch-off criterion > Free (% / s)...** (weight loss in percent per unit of time)

### Timed switch-off

With this switch-off criterion the measurement lasts until the present drying time has elapsed. The display provides you with continuous information in the drying time.

### Performing Test measurements

For performing test measurements to determine a correct switch-off criterion, see Test a Method (page 80).

## 8.1.2 Settings of Display Mode

**Navigation:** Home > Method Definition > Method name > Main measurement parameters > Display mode

With this function you can select the desired type of result display. You also define what type of values are printed on the records.

You can define the following parameters:

Parameter	Explanation	Values
<b>Display mode</b>	Defines the type of value for displaying and printing.	%MC*   %DC   %AM   %AD   g  g/kg MC   g/kg DC   -%MC

\* Factory setting

- **%MC** – Moisture Content (calculated value)
- **%DC** – Dry Content (calculated value)
- **%AM** – ATRO Moisture Content (calculated value)
- **%AD** – ATRO Dry Content (Wet weight, calculated value)
- **g** – Weight in Grams
- **g/kg MC** – Moisture Content (calculated value)
- **g/kg DC** – Dry Content (calculated value)
- **-%MC** – Moisture Content (negative value, calculated value)

### Note

Calculated values are indicated with an asterisk in the display.

Detailed information:

#### %MC – Moisture Content

The moisture content of the sample is displayed (and printed out) as a percentage of the wet weight (WW = initial weight = 100 %). This is the **factory setting**.


During the measurement the value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "%MC" (Moisture Content, e.g. 11.35 %MC) also for the printed results.

$$MC = \frac{WW - DW}{WW} \cdot 100 \%$$

MC = Moisture Content [0...100 %]

WW = wet weight

DW = dry weight



Before drying      After drying

#### %DC – Dry Content

The dry content of the sample is displayed (and printed out) as a percentage of the wet weight (WW = initial weight = 100 %).


During the measurement the value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "%DC" (Dry Content, e.g. 88.65 %DC) also for the printed results.

$$DC = \frac{DW}{WW} \cdot 100 \%$$

DC = dry content [100...0 %]

WW = wet weight

DW = dry weight




Before drying      After drying

### %AM – ATRO Moisture Content<sup>1)</sup>

The moisture content of the sample is displayed (and printed out) as a percentage of the dry weight (DW = final weight = 100 %)

During the measurement the value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "%AM" (ATRO Moisture Content, e.g. 255.33 %AM) also for the printed results.



$$AM = \frac{WW - DW}{DW} \cdot 100 \%$$

AM = ATRO moisture content [0...1000 %]


WW = wet weight

DW = dry weight

### %AD – ATRO Dry Content (Wet weight)<sup>1)</sup>

The wet weight of the sample is displayed (and printed out) as a percentage of the dry weight (DW = final weight = 100 %)

During the measurement the value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "%AD" (ATRO Dry Content, e.g. 312.56 %AD) also for the printed results..



$$AD = \frac{WW}{DW} \cdot 100 \%$$

AD = ATRO dry content [100...1000 %]

WW = wet weight

DW = dry weight

#### <sup>1)</sup> Comment on the ATRO display mode

If the current measured value in the ATRO display mode is greater or less than the predefined limit value (i.e. greater than 999.99 %AD or less than -999.99 %AM), the ATRO result values are limited to 999.99%.

### g – Weight in Grams


The weight of the sample is displayed (and printed out) in grams. With this setting, the Moisture Analyzer is used as a precision balance.

During the measurement current weight is constantly displayed in grams.

### g/kg MC – Moisture Content

The moisture content of the sample is displayed (and printed out) in g/kg of the wet weight (WW = initial weight = 1000 g/kg).

During the measurement the current measured value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "g/kg MC" (Moisture Content, e.g. 11.35 g/kg MC) also for the printed results.



$$MC = \frac{WW - DW}{WW} \cdot 1000 \text{ g/kg}$$

MC = Moisture Content [0...1000 g/kg]

WW = wet weight

DW = dry weight

### g/kg DC – Dry Content

The dry content of the sample is displayed (and printed out) in g/kg of the wet weight (WW = initial weight = 1000 g/kg).


During the measurement the current measured value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "g/kg DC" (Dry Content, e.g. 88.65 g/kg DC) also for the printed results.

$$DC = \frac{DW}{WW} \cdot 1000 \text{ g/kg}$$

DC = dry content [1000...0 g/kg]

WW = wet weight


DW = dry weight



### -%MC – Moisture Content

The moisture content of the sample is displayed (and printed out) as a percentage of the wet weight (WW = initial weight = 100 %).

During the measurement the value is constantly displayed in percent and as a graphical drying curve. The measured value is marked by "-%MC" (Moisture Content, e.g. -11.35 %-MC) also for the printed results and shown as a negative value.



$$MC = -\frac{WW - DW}{WW} \cdot 100 \%$$

MC = Moisture Content [0...100 %]

WW = wet weight

DW = dry weight

### 8.1.3 Settings of Start Weight

**Navigation:** Home > Method Definition > Method name > Main measurement parameters > Start weight

The start weight affects both the duration of the measurement as well as the accuracy of the results. A small weight results in a shorter duration of the measurement but will decrease the accuracy of the result. With this function you can define a start weight so that the samples are approximately of equal weight thus improving the repeatability of the measurements. The weighing-in aid assists you in weighing-in the sample. At most of the samples the target weight is in the range of 2–5 g (plastics 30 g). We recommend to cover the whole surface of the sample pan with a thin uniform layer of sample.

You can define the following parameters:

Parameter	Explanation	Values
<b>Start weight</b>	Defines a start weight so that the samples always have approximately the same weight .	<b>OFF*</b>   <b>ON</b> (0.100...200.000 g)
<b>Start weight tolerance</b>	Defines the tolerance of the <b>Start weight</b> . 10 %, recommended for sample weights up to 5 g.	1...25 % (10 %)*
<b>Weigh-in aid</b>	Defines monitoring of target weight and tolerance. <b>Passive</b> = tolerance is displayed. <b>Active</b> = tolerance is monitored. If the startweight is out of tolerance, the measurement cannot be started.	<b>Passive*</b>   <b>Active</b>

\* Factory setting

## 8.2 Result and Values Handling

**Navigation:** Home > Method Definition > Method name > Result and value handling

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Control limits</b>	Defines the acceptable range for measuring results in the unit of the selected display mode.	<b>see</b> Control limits (page 75)
<b>Resolution</b>	Defines the readability of the built-in analytical balance.	<b>see</b> Resolution (page 76)

### 8.2.1 Control limits

**Navigation:** Home > Method Definition > Method name > Result and value handling > Control limits


With this function you can set warning and intervention limits for the quality and process monitoring. You can also set limits for distinguish passed or failed.

You can define the following parameters:

Parameter	Explanation	Values
<b>Control limits</b>	Defines the acceptable range for the measuring results in the unit of the selected display mode. <b>OFF</b> = no limits applied.	<b>OFF*   ON</b>
<b>T1+ (Upper warning limit)</b>	Defines the upper warning limit in the selected unit of the display mode. Measurement passed with warning (!). Value range in ATRO mode (%AD, %AM) up to 1000.	<b>OFF*   0.01...100.0 (1000)</b>
<b>T1- (Lower warning limit)</b>	Defines the lower warning limit in the unit of the selected display mode. Measurement passed with warning (!). Value range in ATRO mode (%AD, %AM) up to 1000.	<b>OFF*   0.01...100.0 (1000)</b>
<b>T2+ (Upper intervention limit)</b>	Defines the upper intervention limit in the unit of the selected display mode. Measurement failed (X). Value range in ATRO mode (%AD, %AM) up to 1000.	<b>OFF*   0.01...100.0 (1000)</b>
<b>T2- (Lower intervention limit)</b>	Defines the lower intervention limit in the unit of the selected display mode. Measurement failed (X). Value range in ATRO mode (%AD, %AM) up to 1000.	<b>OFF*   0.01...100.0 (1000)</b>

\* Factory setting

## Setting the limits



Limits		1	2	3	4	5	6
<b>T2+ (Upper intervention limit)</b>	(X)	●	●	Off	●	●	Off
<b>T1+ (Upper warning limit)</b>	(!)	Off	Off	Off	●	●	Off
<b>T1- (Lower warning limit)</b>	(!)	Off	Off	Off	●	Off	●
<b>T2- (Lower intervention limit)</b>	(X)	●	Off	●	●	Off	●

- (✓) Measurement is within the warning limits: passed (displayed in green)
- (!) Measurement is between the warning limits and the intervention limits: passed with warning (displayed in yellow)
- (X) Measurement is outside the intervention limit: failed (displayed in red)
- Control limits is off = no limits applied (displayed in blue)

### 8.2.2 Resolution

**Navigation:** Home > Method Definition > Method name > Result and value handling > Resolution

Traditionally, moisture analyzers are operated at a maximum resolution of 1 mg / 0.01 %. The following setting allows you to determine moisture content using the resolution of the built-in analytical balance, which is ten times higher (0.1 mg weight / 0.001 % moisture). The high resolution is especially suitable for samples with low moisture content (lower than 1 %). Careful sample preparation is extremely important for these kind of samples!

#### Note

High resolution is not available for the display mode **ATRO moisture content** or **ATRO dry content**, see Settings of Display Mode (page 72).

You can define the following parameters:

Parameter	Explanation	Values
<b>Resolution</b>	Defines the readability of the built-in analytical balance.	<b>Standard*</b>   <b>High</b>

\* Factory setting

## 8.3 Workflow Handling

**Navigation:** Home > Method Definition > Method name > Workflow handling

With this functions you can define the workflow for the measurement

You can define the following parameters:

Menu item	Explanation	Further Information
<b>Starting mode</b>	Defines how the sample chamber is operated.	<b>see Starting Mode (page 77)</b>
<b>Preheating</b>	Defines the settings for preheating the sample chamber before starting the measurement.	<b>see Preheating (page 77)</b>

### 8.3.1 Starting Mode

**Navigation:** Home > Method Definition > Method name > Workflow handling > Starting mode

In this menu item you can choose whether the sample chamber should operate automatically or manually (e.g. start, stop drying).

You can define the following parameters:

Parameter	Explanation	Values
<b>Starting mode</b>	Defines how the sample chamber is operated.	<b>Automatic*   Manual</b>

\* Factory setting

#### Automatic

Your instrument is set in the factory to the automatic operating mode. This mode can be used for most kind of samples. When closing the sample chamber, the weight of the sample is recorded and the measurement is started.

#### Manual

We advise you to use the manual operating mode for samples which contain readily volatile substances. In contrast to the automatic operating mode, in the manual operating mode the sample chamber does not automatically close when the [Start drying] button is tapped. However, the initial weight (wet weight) important for the determination of the moisture content is recorded. In the manual operating mode you have time for further preparation of the sample (e.g. mixing with quartz sand or even distribution of the sample) while weight losses due to evaporation during the preparation time are measured from the outset. As soon as the sample is ready for drying, press [ $\uparrow\downarrow$ ] key. The automatic sample chamber closes and drying starts. In the manual operating mode you can open the sample chamber during a drying operation. In contrast to the automatic mode, drying will not be stopped but simply interrupted until the automatic sample chamber is closed again.

### 8.3.2 Preheating

**Navigation:** Home > Method Definition > Method name > Workflow handling > Preheating

If necessary, you can activate preheating function to preheat the sample chamber. Because of the short heat-up times with halogen moisture analyzers, no preheating is usually required for standard applications. A preheated instrument can improve the reproducibility and accuracy of the results, since the instrument is in the same climatic state with every measurement. Preheating will only be executed until time of measurement (**Manual**), in standby mode even after the measurement.

You can define the following parameters:

Parameter	Explanation	Values
<b>Preheating</b>	Defines the settings for preheating the sample chamber (standby temperature) before starting the measurement.  OFF = no preheating applied.	<b>OFF*   ON   Manual   Standby</b>

\* Factory setting

## Manual

Before a measurement can be started, the instrument prompts the user to activate the function preheating. The instrument indicates, when it is enough preheated to start the measurement. The measurement can also be performed during the preheating phase by tapping **Stop preheating**. In this case, the duration of preheating will be recorded. After a maximal preheating time of 1 hour, preheat will be off.

You can define the following parameters:

Parameter	Explanation	Values
<b>Temperature</b>	Defines the standby temperature.	40...100 °C (40 °C)*

\* Factory setting

## Standby

The instrument indicates, when it is enough preheated to start the measurement. The measurement can also be performed during the preheating phase by tapping **Stop drying**. In this case, the duration of preheating will be recorded.

The function **Duration** allows you to deactivate preheating at a preselected time period after measurement. The feature **Turn-off time** allows to disable preheating at a defined clock time.

You can define the following parameters:

Parameter	Explanation	Values
<b>Temperature</b>	Defines the standby temperature.	40...100 °C (40 °C)*
<b>Duration</b>	Defines the time which the instrument is maintained at standby temperature for a limited amount of time after measurement (time out).	<b>Hours   Minutes</b> (3 h)*
<b>Turn-off time</b>	Defines the clock time at which <b>Preheating</b> will be off.	<b>OFF*   Hours : Minutes</b>

\* Factory setting

## 8.4 General Method Properties

Navigation: Home > Method Definition > Method name > General method properties

### 8.4.1 Method name

Navigation: Home > Method Definition > Method name > General method properties > Method name

You can define the following parameters:


Parameter	Explanation	Values
Method name	Renaming a method. Name should be unique and unambiguous.	any

## 8.5 Test a Method

### Test a method

This function allows you to test the settings during the definition phase of a method. Testing is possible at any time. Test measurements are recorded in the journal and marked as test results. If you wish to work with the switch-off criterion «weight loss per unit of time» and are not familiar with the behavior of the sample, the test measurement will help you select the suitable setting. For more information about switch-off criteria, **see** Settings of Switch-off Criterion (SOC) (page 70).

The diagram illustrates the progress of a drying. The points at which the individual switch-off criteria were reached (1-5) are marked.



During this measurement, the measured values are recorded the switch-off criteria 1 to 5 and maybe one of a free-defined switch-off criterion. The measurement terminates after the defined time (default 30 minutes). Note that the start weight affects the switch-off criterion. The test time can also be switched off. In this case the measurement terminates after reaching the predefined switch-off criterion. Nevertheless, all switch-off criteria are recorded.

By comparing the measured values with values of a reference method e.g. drying oven and the standard deviation, you can define the appropriate parameter settings. For more information see the application brochure «Guide to Moisture Analysis».

Carry out all measurements under **Home > Method Definition > Method name > Tests** before releasing a method. The results of test measurements are specifically marked.

#### Attention

Before releasing the method, check if the determined switch-off criterion is set.

#### Performing a Test measurement

You perform a test measurement just like any other measurement. How to perform the measurement **see** Measurement (page 81).

#### Changing the test time

- Work screen for testing is displayed.
- 1 Tap **Test time** in the work screen.
  - ⇒ **Test time in min** appears.
- 2 Confirm with **OK**.

#### Displaying the parameter

- Work screen for testing is displayed.
- Tap the parameter in the work screen.
  - ⇒ The parameter list appears.

#### Printing results of the determined switch-off criteria

For a printout example, **See** Information on Printouts (page 87) section «Special events».

#### Displaying results of the determined switch-off criteria

**See** Graphical Evaluations of Measurement Results (page 85)

## 9 Measurement

This function offers you to perform a measuring using previously defined methods. After choosing the measurement method, the measurement process can be started. The work screen guides you step by step through the measuring process.

The following functions are available:

- On the work screen, you can create a shortcut. This allows you to start a method directly from the home screen.  
**See** Using Shortcuts (page 83).
- After completion of a measuring you can perform a further measuring with same method by tapping [**Next Sample**] or with an other method by tapping [**Measurement**].
- For graphical evaluations of measurement results tap [**Results**]. If you have defined the control limits in the method, passed, warned or failed status is shown.  
**See** Results (page 85).
- A detailed overview of the method parameter can you call up by tapping the parameter panel.  
**See** Work Screen (page 22).

### 9.1 Performing a Measurement

You are now familiar with all the parameters of your instrument and have defined all values for your sample. The instrument is now ready for the determination of your samples. In this Section you will learn how to perform measurements and how to stop the measurement process.

#### Switching on

- The instrument must be connected to the power supply for approximately 60 minutes in order to reach operating conditions.
- 1 To switch on the Instrument, press [].
  - 2 Log-in with your password, if needed.




#### Selecting method for measurement

- 1 Tap **Measurement**.  
⇒ The methods list is displayed.
- 2 Select the method to determine your sample.  
⇒ The work screen of the method appears.  
⇒ The sample chamber opens automatically.

#### Placing sample pan

- The display now prompts you to load the empty sample pan and tare the balance.
- 1 Place the empty sample pan in the sample pan handler.
  - 2 Place the sample pan handler in the sample chamber. Ensure that the tongue of the pan handler fits exactly in the slot of the draft shield element. The sample pan must lie flat in the pan holder.



#### Note

We advise you to work with the sample pan handler at all times. The pan handler is ergonomic, automatic positioning, safe and provides protection against possible burns due to the hot sample pan.


## Taring balance

- Tap [→0/T←].
  - ⇒ The sample chamber closes automatically for taring.
  - ⇒ When taring is completed, the sample chamber opens automatically.



## Starting measurement

- After taring, the display prompts you to add the sample to the sample pan.
  - 1 Add the sample to the sample pan. If you have defined a start weight, weigh the sample using the weighing-in aid.
  - 2 Tap [**Start drying**].
    - ⇒ The sample chamber closes automatically.
    - ⇒ The drying process starts automatically.



## Drying process

You can follow the measurement process on the display, **see Work Screen** (page 22).

- The drying process is continuously displayed graphically.
- The current temperature in the heating module is displayed as well as the elapsed drying time and the current drying value.
- The display shows the selected settings.
- The drying process can be aborted by tapping [**Stop drying**].

At the end of the drying process you can read the moisture content of your sample on the display. If you have defined the control limits in the method, passed, warned or failed status is shown.

## Removing Sample


### CAUTION



### Danger of burns

Sample, sample pan and sample pan holder may still be hot.

- The drying process is completed.
  - The sample chamber is open (opens automatically).
- 1 Carefully remove the sample pan handler from the sample chamber.
- Note**
- To remove the sample pan from the handler, lift the pan slightly from below and remove it from the handler.
- 2 • To perform a further measurement with the current method, tap [**Next Sample**].
    - To perform a measurement with a new method, tap [**Measurement**].
    - To return to the home screen, press [**Home**].



### Stop drying

When you stop the measuring process by tapping [Stop drying], you can choose between two possibilities:

- **Abort without saving**

Abort without saving of any data collected until now.

- **Abort measurement and save data**

Already sampled data are stored and an entry will be made in the results. The result is marked as aborted.

### Adding a comment

At the end of a measurement you can add a comment to the result of the measurement. This comment is stored in the measurement result and can be printed. A comment can only be entered before leaving the current measurement.

1 To create a comment, tap [Note].


⇒ The keyboard dialog appears.

2 Enter a comment.

3 Confirm with [OK].

## 9.2 Work with Weighing-in Aid

The weighing-in aid can be defined for each method and facilitates weighing in of the sample to a target value. This is particularly necessary if you require all the samples of a method you wish to process to have same weight in order to improve the repeatability of the measurement results. In addition, the weighing-in aid can be set as active so that the drying process cannot be started if the weight of sample is outside the set tolerance. You are therefore compelled to weigh-in the correct quantity of sample. If all sample weighed are within tolerances then this will improve the repeatability. The weighing-in aid is available only if start weight has been activated. For further information see Settings of Start Weight (page 74).



Icon	Function
	Lower weight limit (tolerance range)
	Target weight
	Upper weight limit (tolerance range)

## 9.3 Using Shortcuts

Navigation for managing shortcuts: Home > Measurement > Method name > []

Shortcuts allow you to start methods directly from the home screen. Shortcuts are user-specific, i.e. each individual user can have his own shortcuts for the most common tasks.

You can define the following parameters:

Parameter	Explanation	Values
<b>Shortcut name</b>	Defines a name for the shortcut. It is recommended to choose a short name because only approx. 8 characters are displayed on the shortcut. Name should be unique and unambiguous.	<b>any</b>
<b>Method name</b>	Shows the name of the method. The name of the method is the target of the shortcut and can not be changed.	<b>none</b>

#### Defining a shortcut

- Menu **Measurement** is activated.
  - The method is selected.
- 1 Tap [**¶**].  
⇒ Window **My shortcuts** appears.
  - 2 Tap **Add a shortcut to my home for this method....** (To abort, tap [X].)  
⇒ **New shortcut** appears.
  - 3 To enter a name for the shortcut if needed, tap **Shortcut name**.
- Note**  
It is recommended to choose a short name because only approx. 8 characters are displayed on the shortcut. Name should be unique and unambiguous.
- 4 Confirm with [**OK**].
  - 5 To store the setting, tap [**Save**].  
To abort, tap [**Cancel**].  
⇒ The shortcut is added to the home screen.

#### Editing a shortcut

- The method is selected.
- 1 Tap [**¶**].  
⇒ Window **My shortcuts** appears.
  - 2 Tap **Edit this shortcut....** (To abort, tap [X].)  
⇒ **Shortcut properties** appears.
  - 3 To edit the name of the shortcut, tap **Shortcut name**.
  - 4 Confirm with [**OK**].
  - 5 To store the setting, tap [**Save**].  
To abort, tap [**Cancel**].

#### Removing a shortcut


- The method is selected.
- 1 Tap [**¶**].  
⇒ Window **My shortcuts** appears.
  - 2 Tap **Edit this shortcut....** (To abort, tap [X].)  
⇒ **Shortcut properties** appears.
  - 3 To remove the shortcut, tap [**Remove**].  
⇒ A message window appears.
  - 4 Confirm with [**Remove**]. (To abort, tap [**Cancel**].)  
⇒ The shortcut is removed from the home screen.

# 10 Results

## 10.1 Graphical Evaluations of Measurement Results

**Navigation:** Home > Results

This function allows you to manage and evaluate measurement results.



## 1 Method list

- Tap the method you want to evaluate.  
⇒ The journal view appears.

## 2 Journal view

The journal view allows you to start different graphical evaluations from a measurement series. You can perform the following functions:

- To start **filter function**, tap [▼].  
⇒ The filter menu appears.
- To start **chart view**, tap [**Chart**].  
⇒ The chart view of the series of measurement appears (4).
- To start **graphic view**, tap a measurement result.  
⇒ The graphic view appears (5).

## 3 Filter menu

The filter function allows you to evaluate the measurement series according to various criteria. You can select the following criteria:

- **All (No filter)**
- **Today**
- **This week**
- **Date range (Start - End)...**
- **Last 10 measurements\***
- **Last 20 measurements**

- Tap [X] to close filter menu.

\* Factory setting

## 4 Chart view

This view allows you to display the results of a series of measurements depending on the filter settings. If you have defined the control limits in the method, they are diagramed in the results.

The  marked measuring point is displayed with date, time, and the measurement result. You can perform following functions:

- To jump forward to the next measurement result, tap [ -> ].
- To jump backwards to the previous measurement result, tap [ <- ]. Alternatively, tap directly on the desired measurement point.
- To recall the full measurement curve of the corresponding measurement, tap [  ].

## 5a Graphics view

With this function you can display a graphical view of the detailed results of a single measurement. If you have defined the control limits in the method, passed, warned or failed status is shown, **see Control limits** (page 75).

You can perform the following functions:

### Printing result

- To print the result, tap [].

### Exporting result

- To export the result, tap [**Export**].

**See** Exporting Results (page 88).

### **Deleting result**

- To delete this measurement result, tap [Delete] (depending on user rights).

### **More data**

- To display more measurement data, tap [More data]

### **5b Displaying results of test measurements**

For test measurements **see** Test a Method (page 80).

This view allows you to display the results of the determined switch-off criteria. Each criterion is marked as a measuring point and displayed with its result. You can perform following functions:

- To jump forward to the next measurement result, tap [ -> ].
- To jump backwards to the previous measurement result, tap [ <- ]. Alternatively, tap directly on the desired measurement point.

## **10.2 Information on Printouts**

The illustrations in this chapter show examples of a standard measurement printout (factory setting) and a short measurement printout. The level of detail on the printouts depends on the selected settings in the menu.

**Structure of the standard printout type**

```
-MOISTURE DETERMINATION-
METTLER TOLEDO
Halogen MoistureAnalyzer

Type HX204
SNR(Drying Unit)
B206683647
SNR(Terminal)
B206683647
SW(Drying Unit) 1.10
SW(Terminal) 1.20

Method name NEG
Drying prog Standard
Drying temp 105 °C
Switch Off 3(1mg/50s)
Display mode %MC
Start weight OFF
Control limits OFF
Resolution Standard
Start mode Automatic
Preheating OFF

User name Administrator
Start weight 0.487 g
Total time 0:22 min
Dry Weight 0.470 g

Moisture content
0.017 g
End result 1.79 %MC

Note
Signature
.....
20.11.2012 12:01
----- END -----
```

**Structure of the short printout type**

```
-MOISTURE DETERMINATION-
METTLER TOLEDO
Halogen MoistureAnalyzer

Type HX204
SNR(Drying Unit)
B206683647
SNR(Terminal)
B206683647
SW(Drying Unit) 1.10
SW(Terminal) 1.20

Method name: NEG
Drying Prog Standard
Drying Temp 105 °C
Switch Off 3(1mg/50s)

User name Administrator
Start weight 0.487 g
Total time 0:22 min
End result 1.79 %MC
Note
14.11.2012 12:01
----- END -----
```

### Special events

The **sample chamber was opened and closed** during drying process. When the sample chamber is open, drying is interrupted and then continued when the chamber is closed.

01:00 min	2.26 %MC
01:20 min	opened
01:28 min	closed
02:00 min	3.49 %MC

The **drying process has been aborted** by tapping **[Stop drying]** and the measurement result at the time of the abort is not recorded as it could be wrong.

01:00 min	2.26 %MC
02:00 min	3.49 %MC
ABORTED	
14.10.2011	12:01

### Printing the test measurement

During the test measurement a record is printed which explains exactly when and with what measurement result each switch-off criterion was reached.

Switch-off crit. 3	
Time	01:21 min
Dry weight	3.385 g
Moisture content	0.53 %MC

## 10.3 Exporting Results

Results can be exported to an external storage device e.g. memory stick. This data in CSV format can be imported into e.g. MS Excel for further evaluations.

### Note

Results cannot be imported in a Moisture Analyzer.

### Single result export

You can define the following parameters:

Parameter	Explanation	Values
<b>File name</b>	Defines the name of the new data file.	<b>any</b>
<b>Location</b>	Finds the location on the storage device.	<b>Browse and select</b>
<b>File type</b>	Defines the type of the data file.	<b>csv*</b>

\* Factory setting

### Multiple result export

You can define the following parameters:

Parameter	Explanation	Values
<b>File name prefix</b>	Defines the name of the new data file. Date and time are automatically added by the system.	<b>any</b>
<b>Location</b>	Finds the location on the storage device.	<b>Browse and select</b>
<b>Export selection</b>	Custom selection of multiple results for the export from selected measurements. The selection can be made via the filter function.	Selection: <input type="checkbox"/> <input checked="" type="checkbox"/>
<b>Export content</b>	Defines the content of the multiple results export.  <b>Summary export (one file, no intermediate values):</b> Results as summary report in one file. <b>Multiple export (one file per measurement):</b> Results with intermediate measurement values as separate files with the same layout as for the single result export.	<b>Summary export   Multiple export</b>

<b>File type</b>	Defines the type of the data file.	<b>csv*</b>
------------------	------------------------------------	-------------

\* Factory setting

#### Note

- **Summary export**

- The summary export contains method parameters and the end results per measurement. The intermediate values are not exported.
- If the method has step drying, the summary export also includes the results per step.
- If the test measurement was executed, then the summary export also includes the results for each switch-off criteria reached during the test measurement.

- **Multiple export**

- The multiple export contains method parameters, method data, intermediate values and end results per measurement.
- Each measurement is exported as a single file.

#### Procedure

- ▶ Result is activated.
  - ▶ An external storage device is connected e.g. memory stick.
- 1 To start, tap [**Export**].  
⇒ **Export Results** appears.
  - 2 Tap **Location > Browse and select**.  
⇒ **Location** appears.
  - 3 Select location for file and confirm with [**OK**].
  - 4 Enter new file name, if needed.
  - 5 To start export, tap [**Export**].

## 11 Maintenance

---



### WARNING

#### Risk of electric shock

The instrument must be disconnected from the power supply, before cleaning or other maintenance work to be performed.

---

#### Note

- The thermal overload protection can not be reset by the user.
- The halogen lamp can not be replaced by the user.

In such cases, contact your METTLER TOLEDO representative.

## 11.1 Cleaning

---



### CAUTION

#### Danger of burns

The interior parts of the heating module as well as the parts in the sample chamber could be very hot.

- Wait until the heating module has cooled down completely.
- 

To obtain precise measurement results, we recommend you to clean the temperature sensor and the protective glass of the halogen lamp regularly. Please note the following directions for cleaning your instrument.

#### General

Your Moisture Analyzer is made from high quality, resistant materials and can therefore be cleaned with a commercially available, mild cleaning agent e.g. isopropanol.

#### Attention

- Use a lint-free cloth for cleaning.
- Ensure that no liquids enters the interior of the instrument.

#### • Heating Module

Clean the exterior of the heating module with a mild cleaning agent although the housing is extremely rugged and resistant to solvents.

#### • Terminal

On no account use cleaning agents, which contain solvents or abrasive ingredients, as this can result in damage to the terminal overlay.


- Never open the housing of the instrument – they contain no components, which can be cleaned, repaired or replaced by the user.

#### Note


After the temperature sensor or the protective glass have been cleaned, we recommend adjusting the heating module using the temperature adjustment kit, **see** Temperature Adjustment (page 57).

### 11.1.1 Sample Chamber

- ▶ Sample chamber is open.
- 1 Remove the sample pan handler (1), the sample pan holder (2) and the draft shield (3) for cleaning.
  - 2 Carefully remove any deposits from the black temperature sensor (4).



### 11.1.2 Heating Module



- 1 Reflector ring
- 2 Protective glass
- 3 Reflector with inspection window glass
- 4 Halogen lamp


To clean the protective glass, the reflector as well as the reflector ring, you should first open the heating module.

#### Attention

Avoid touching the round halogen lamp. If you have to remove any splashes, deposits, or spots of grease from the halogen lamp, it is advisable to use a weak organic solvent such as, for example ethanol. Ensure that the lamp is cool. **Do not remove the halogen lamp!**

#### Opening heating module for cleaning

- Sample chamber is open.
- 1 Inside, there is a locking device on each side. Push both outwards (together) for unlocking.  
**Note**  
Do not hold the module while unlocking it.  
⇒ The upper part has been unlocked on both sides.
- 2 Open the heating module.




#### Removing reflector ring for cleaning

##### Note


For cleaning the protective glass, removing the reflector ring is not mandatory.

- Heating module is open.
- 1 On both sides and at the same time, pull the two lugs outwards.
- 2 Unhook the ring and remove it from the bracket.




#### Removing reflector with inspection window glass for cleaning

- Reflector ring is removed.
- 1 To unlock, pull the spring clip forwards.
- 2 Pull out the reflector upwards off the bracket.



### Removing protective glass for cleaning


- Reflector is removed.
- Pull out the protection glass upwards off the bracket.



### Reassembling after cleaning

Reassemble all parts in the opposite order.

- All parts are cleaned.
- 1 Insert the protective glass.
- 2 Insert the reflector with inspection window glass (until it clicks).  
**Note**  
The lamp must be located in front of the reflector. Do not touch the lamp with your fingers.
- 3 Insert the reflector ring.  
**Attention**  
Observe the correct position! Assure that the ring is properly fitted.
- 4 Close the heating module (until it clicks).




### 11.1.3 Fan Grill

The air inlet of the fan is located at the rear of the instrument and its exterior should be cleaned from time to time to free it from any dust deposits.

## 11.2 Dust Filter

If you use the Moisture Analyzer in a dusty environment with an dust filter, check the filter at regular intervals. Replacement Filters **see** Accessories and Spare Parts (page 105).

- Replace the filter, if needed.



## 11.3 Replacing Power Line Fuse



### CAUTION

#### Safety risk or damage of the instrument

Do not use a fuse of a different type or rated value, or short out (bridge) the fuse, because this can put your safety at risk and damage the instrument!


If the display of your terminal remains dark after switching on, in all probability the power line fuse of the drying unit is blown.

The power line fuse is located on the back of the drying unit. To change the fuse, proceed as follows:

- 1 Pull out the power cord.
- 2 Slide out the fuse holder (1) with a suitable tool such as a screwdriver.
- 3 Remove the fuse (3) and check its condition.
- 4 If the fuse is blown, replace the fuse with one of the same type and the same rated value (5 x 20 mm, T6.3H 250 V).

**Note:**

A spare fuse is located in the holder (2).



Fuse **see** General Technical Data (page 99)

## 11.4 Disposal

In conformance with the European Directive 2002/96/EC on Waste Electrical and Electronic Equipment (WEEE) this device may not be disposed of in domestic waste. This also applies to countries outside the EU, per their specific requirements.



Please dispose of this product in accordance with local regulations at the collecting point specified for electrical and electronic equipment. If you have any questions, please contact the responsible authority or the distributor from which you purchased this device. Should this device be passed on to other parties (for private or professional use), the content of this regulation must also be related.

Thank you for your contribution to environmental protection.

## 12 Troubleshooting

Errors can occur during operation of your instrument. This section describes how you can rectify these errors.

### 12.1 Error Messages

Most error messages appear in plain text directly in the respective application, and usually accompanied by a text describing how to correct the error. Error messages of this type are self-explanatory and therefore are not mentioned below. The following error messages can appear instead of the weighing result.

Error Message	Cause	Rectification
<b>Weight display</b>		
	<b>Overload</b> – The weight on the pan exceeds the weighing capacity of the balance.	– Reduce the weight of the sample.
	<b>Underload</b> – Sample pan holder is missing.	– Insert sample pan holder. If needed, reboot the system by disconnecting and connecting to the mains.
	<b>Weight display flashes / Out of zero range</b> – When the instrument was switched on or upon zeroing, one or more limits were exceeded. The usual reason for this message to appear is when there is a weight on the weighing pan when the balance is switched on.	– Remove the weight.
<b>Adjustment</b>		
<b>Unstable weight.</b>	<b>No stability</b> during adjustment.	<ul style="list-style-type: none"><li>• Ensure ambient conditions and an optimum location.</li><li>• Take care that no part of the sample or the sample pan touches the draft shield or the sample pan handler.</li><li>• Ensure that the sample pan holder is correctly installed as well as not defect.</li><li>• Highly volatile substances in the sample also prevent a stable weighing result being detected since the sample is continuously losing weight.</li></ul>
<b>Weight out of range.</b>	Either <b>no weight</b> , or the <b>wrong weight</b> , has been placed on the sample pan during adjustment. (This message is also displayed if you do not remove the weight when prompted to do so by the instrument.)	– Repeat the adjustment process and load the required adjustment weight.

### 12.2 Status Messages

Status messages are displayed by means of small icons in the status bar of the display. For further information see Status Message Icons (page 17). The status icons indicate the following:

Cause	Rectification
	<p>Hot surface Indicates that the temperature inside the sample chamber is over approximately 50°C. The parts in the sample chamber and the sample itself can be very hot and there is a risk of burns.</p>
	<p>The built-in level sensor has determined that the instrument is not correctly leveled.</p> <ul style="list-style-type: none"> <li>– Level the instrument immediately. <b>See</b> Leveling Drying Unit (page 27)</li> <li>⇒ If the instrument is leveled correctly, the icon disappears.</li> </ul>
	<p>The instrument would like to carry out a fully automatic FACT adjustment but is unable because another operating sequence is running.</p>
	<p>The battery in your instrument must be replaced. This battery ensures that the date and time are not lost when the instrument is disconnected from the power supply.</p>
	<p>Your instrument is due for servicing.</p> <ul style="list-style-type: none"> <li>– Contact your METTLER TOLEDO representative as soon as possible.</li> <li>⇒ A service technician will change the battery.</li> <li>– Contact your METTLER TOLEDO representative as soon as possible to have a technician service your instrument.</li> </ul>

## 12.3 What to Do if...

Symptom	Countermeasure
Display remains dark after switching on	<ul style="list-style-type: none"> <li>• Ensure that the terminal is properly connected to the drying unit.</li> <li>• Ensure that the instrument is connected to the power supply and the power is on.</li> <li>• Check the power line fuse of the drying unit and replace if necessary, <b>see</b> Replacing Power Line Fuse (page 94).</li> <li>• If the problem persists, contact a METTLER TOLEDO representative.</li> </ul>
Keys and buttons do not respond	<ul style="list-style-type: none"> <li>• Reboot the system by disconnecting and connecting to the mains.</li> <li>• If the problem persists, contact a METTLER TOLEDO representative.</li> </ul>
Printer that is connected does not print	<ul style="list-style-type: none"> <li>• Ensure that the printer is on and enabled in the menu. <b>See</b> Peripherals (page 36)</li> <li>• Check the printer settings. <b>See</b> Recommended Printer Settings (page 110).</li> </ul>
Incorrect characters are printed	<ul style="list-style-type: none"> <li>• Change the bit/parity setting of the printer and the instrument to <b>8/NO</b>.</li> <li>• Check if both instruments have the same baud rate setting, <b>see</b> Peripherals (page 36).</li> <li>• Use the correct character sets, <b>see</b> Recommended Printer Settings (page 110).</li> </ul>
Measurement takes too long	<ul style="list-style-type: none"> <li>• You have selected an unsuitable switch-off criterion, <b>see</b> Settings of Switch-off Criterion (SOC) (page 70).</li> <li>• An excessive amount of sample can also be the cause of slow drying, likewise samples which tend to form a skin which hinders vaporization. Perform a measurement at higher temperature.</li> <li>• Enlarge the surface of the sample, e.g. by crushing or grinding.</li> <li>• Use absorbent glass fiber filters for liquids.</li> <li>• If the sample is very temperature sensitive and decomposes, reduce the temperature.</li> <li>• If measuring is unstable, check correct positioning of pan, sample handler, sample, draft shield or sample holder.</li> </ul>
Instrument does not heat after the start	<ul style="list-style-type: none"> <li>• Halogen lamp is defective or the heating module is overheated and the thermal overload protection has switched off the heating. In case, contact your METTLER TOLEDO representative.</li> </ul>

Symptom	Countermeasure
Measurement results are not repeatable	<ul style="list-style-type: none"> <li>• Support on which the instrument is standing is not sufficiently stable. Use a stable support.</li> <li>• Surroundings are very unstable (e.g. vibrations, air draft, humidity). Provide better environmental conditions.</li> <li>• Sample has more or less moisture between sampling and starting the drying process.</li> <li>• Sample is not evenly dispersed on the pan.</li> <li>• Start weight has not always the same value.</li> <li>• Samples are not homogeneous, i.e. they have different compositions. The more inhomogeneous a sample, the larger the amount of sample needed to obtain a repeatable result.</li> <li>• Selected drying time is too short for the "Timed switch-off" criterion. Extend the drying time or select a suitable switch-off criterion "Weight loss per unit of time".</li> <li>• Sample does not become completely dry (e.g. owing to skin formation). Dry the sample with the aid of glass fiber discs.</li> <li>• Selected temperature is too high and the sample has oxidized or decomposed. Lower the drying temperature.</li> <li>• Sample boils and the splashed drops continuously change the weight. Lower the drying temperature.</li> <li>• Granulation is not homogeneous or too large.</li> <li>• Insufficient heating power because the protective glass of the halogen lamp is dirty. Clean the protective glass, <b>see</b> Cleaning (page 90).</li> <li>• Temperature sensor is contaminated or faulty. Clean the temperature sensor, <b>see</b> Cleaning (page 90).</li> <li>• If the problem persists, contact a METTLER TOLEDO representative.</li> </ul>

## 13 Technical Data

### 13.1 General Technical Data

#### Drying Unit

Heating Module	Halogen ring-shaped radiator
Temperature range	40–230 °C
Temperature step	1 °C
Temperature programs	standard, rapid, gentle, step

#### Balance

Maximum load	200 g
Readability	1 mg / 0.1 mg
Minimum sample weight	0.1 g
Weighing technology	Monobloc
Adjustment	FACT, internal weight, external weight

#### Moisture Content

Readability	0.01%
Readability, fine range	0.001%
Repeatability (sd) with 2 g sample	max. 0.05%
Repeatability (sd) with 10 g sample	max. 0.01%

#### Materials

##### Drying Unit

Housing	Plastic, PBT, Crastin SO653-GB20
Inspection window grill	Plastic, PEEK-HT G22 (UL94-VO)
Protective glass	Glass ceramics
Halogen lamp	Quartz glass
Reflector	Stainless steel, X2CrNiMo17-2 (1.4404)
Reflector bracket	Plastic, PEEK-HT G22 (UL94-VO)
Draft shield, interior bottom plate	Stainless steel, X2CrNiMo17-2 (1.4404)

##### Terminal

Top housing	EN ZL-ZnAl4Cu1 (EN ZL-0410)
Bottom housing	PA12 GB30

#### Protection and Standards

Overvoltage category	Class II
Degree of pollution	2
Standards for safety and EMC	see Declaration of Conformity (part of standard equipment)
Range of application	for use in dry interior rooms

#### Environmental Conditions

Height above sea level	up to 4000 m
Ambient temperature range	5 °C to 40 °C
Relative air humidity	10% to 80% at 31 °C, linearly decreasing to 50 % at 40 °C, noncondensing

Warm-up time At least 60 minutes after connecting the instrument to the power supply; when switched on from standby, the instrument is ready for operation immediately.

### Power Supply

110 V AC Version	100 V–120 V, 50/60 Hz, 4 A
230 V AC Version	220 V–240 V, 50/60 Hz, 2 A
Voltage fluctuations	-15%+10%
Power load	max. 450 W during drying process
Power line fuse	5 x 20 mm, T6.3H 250 V

### Interfaces

Drying Unit	1x System (Terminal – drying unit)
Terminal	<ul style="list-style-type: none"><li>• 1 x RS232C (9-pin socket)</li><li>• 2x USB Host (Type A socket), USB 1.1 Supported memory sticks up to 32 GB</li><li>• 1x USB Device (Type B socket), USB 1.1</li><li>• 1x Slot for memory cards SD/SDHC up to 32 GB (SDXC not supported)</li></ul>

### Data

Export data format of results	*.CSV Comma-separated values (CSV) file
-------------------------------	--

### Hardware

#### Drying unit

Sample chamber opening/closing	Motorized
Leveling	2 leveling screws, Level indicator and Inclinometer
Sample pan	Ø 90 mm
Maximum height of sample	15 mm
Thermal overload protection	Bimetallic-element switch in heating module
Dimensions (w x h x d)	199 x 139 x 428 mm <b>See</b> Dimensions (page 102)
Weight, ready to measure	6.8 kg


#### Terminal

Display	WVGA color display, resistive touch-sensitive
Reading angle	Adjustable, 2 folding feet
Dimensions (w x h x d)	200 x 63.5/79.5 x 134.5 mm <b>See</b> Dimensions (page 102)
Weight	1.2 kg

### 13.1.1 Explanatory note to periodic inspections in accordance with EU Directive 2001/95/EC

This instrument is provided with a 3-pin plug. The earth conductor is led into the instrument and connected to the bottom and the rear panel. The other accessible metal parts are not connected to the earth conductor. These parts are reinforced insulated and must not be connected to the earth conductor according to current European standards.

The earth connection must be checked on the metallic rear panel.




Further information about conformance of this instrument can be found in the Declaration of Conformity which is coming with the product or can be downloaded from the internet.

► [www.mt.com/hxhs](http://www.mt.com/hxhs)


## 13.2 Dimensions

(all dimensions in mm)

**Drying Unit**



## Terminal




## 13.3 Interfaces Specification


### 13.3.1 RS232C

Schematic	Item	Specification
	Interface type	Voltage interface according to EIA RS-232C/DIN66020 CCITT V24/V.28)
	Max. cable length	15 m
	Signal level	Outputs: +5 V ... +15 V ( $R_L = 3-7 \text{ k}\Omega$ ) -5 V ... -15 V ( $R_L = 3-7 \text{ k}\Omega$ ) Inputs: +3 V ... +25 V -3 V ... -25 V
	Connector	Sub-D, 9-pole, female
	Operating mode	Full duplex
	Transmission mode	Bit-serial, asynchronous
	Transmission code	ASCII
	Baud rates	600, 1200, 2400, 4800, 9600, 19200, 38400 (software selectable)
	Bits/parity	7-bit/none, 7-bit/even, 7-bit/odd, 8-bit/none (software selectable)
	Stop bits	1 stop bit
	Handshake	None, XON/XOFF, RTS/CTS (software selectable)
	Power supply for 2nd display	+ 12 V, max 40 mA (software selectable, 2nd display mode only)

### 13.3.2 USB Host


Schematic	Item	Specification	
	Standard	In conformity with USB Specification Revision 1.0/1.1	
	Speed	Full speed 12 Mbps (requires shielded cable)	
	Power usage	Max. 500 mA	
	Connector	Type A	
	Pin assignment	1	VBUS (+5 V DC)
		2	D- (Data -)
		3	D+ (Data +)
		4	GND (Ground)
	Shell	Shield	

### 13.3.3 USB Device

Schematic	Item	Specification											
	Standard	In conformity with USB Specification Revision 1.1											
	Speed	Full speed 12 Mbps (requires shielded cable)											
	Function	CDC (Communication Device Class) serial port emulation											
	Power usage	Suspended device: Max 10 mA											
	Connector	Type B											
<table border="1"> <tr> <td>1</td> <td>VBUS (+5 VDC)</td> </tr> <tr> <td>2</td> <td>D- (Data -)</td> </tr> <tr> <td>3</td> <td>D+ (Data +)</td> </tr> <tr> <td>4</td> <td>GND (Ground)</td> </tr> <tr> <td>Shield</td> <td>Shield</td> </tr> </table>	1	VBUS (+5 VDC)	2	D- (Data -)	3	D+ (Data +)	4	GND (Ground)	Shield	Shield			
1	VBUS (+5 VDC)												
2	D- (Data -)												
3	D+ (Data +)												
4	GND (Ground)												
Shield	Shield												


## **14 Accessories and Spare Parts**

Description	Part No.
<b>Power supplies</b>	
	Country-specific 3-Pin power cable with grounding conductor.
Power cable AU	00088751
Power cable BR	30015268
Power cable CH	00087920
Power cable CN	30047293
Power cable DK	00087452
Power cable EU	00087925
Power cable GB	00089405
Power cable IL	00225297
Power cable IN	11600569
Power cable IT	00087457
Power cable JP	11107881
Power cable TH, PE	11107880
Power cable US	00088668
Power cable ZA	00089728
<b>Cables for RS232C interface</b>	
	RS9 – RS9 (m/f): connection cable for PC, length = 1 m
	11101051
<b>Cables for USB interface</b>	
	USB (A –B) connection cable for connection to PC, length = 1 m
	12130716
<b>Cables for terminal</b>	
	Terminal cable, length = 0.68 m
	30003971
<b>Printers</b>	
	RS-P25 printer with RS232C connection to instrument
	11124300
Paper roll, set of 5 pcs	00072456
Paper roll, self-adhesive, set of 3 pcs	11600388
Ribbon cartridge, black, set of 2 pcs	00065975




RS-P42 printer with RS232C connection to instrument	00229265
Paper roll, set of 5 pcs	00072456
Paper roll, self-adhesive, set of 3 pcs	11600388
Ribbon cartridge, black, set of 2 pcs	00065975


### Sample Pans



Aluminum sample pan, HA-D90, set of 80 pcs 00013865




Professional aluminum sample pan, extra strong, set of 80 pcs 11113863



Stainless steel reusable sample pan 6 mm, DA-DR1, set of 3 pcs 00214462


### Adjustment Parts



Certified adjustment weight, 100 g (F1) 11119531



OIML / ASTM Weights (with calibration certificate) see [www.mt.com/weights](http://www.mt.com/weights)




HX/HS Temperature adjustment kit, certified 30020851



SmartCal™, Moisture Analyzer Reference Substance  
cSmartCal™, certified, 12 tests 30005793  
cSmartCal™, certified, 24 tests 30005791  
SmartCal™, 12 tests 30005792  
SmartCal™, 24 tests 30005790


### **Anti-theft devices**



Steel cable


11600361

### **Miscellaneous**




Glass fiber filter (for Liquids), set of 100 pcs

00214464




Dust filter, set of 50 pcs

30020838




Protective cover for Terminal

30003957




Transport case

30020836



Stand for terminal


30018474



Printer holder for mounting on the stand for terminal.








30066692

### **Spare Parts**



Sample pan handler

30020852

	Draft shield	30007150
	Sample pan holder	11148108
	Reflector without inspection glass	11148330
	Inspection glass for reflector	11148421
	Reflector ring	30006700
	Protective glass	11148416
	Leveling foot	11106323


## 15 Appendix

### 15.1 How to Obtain Best Results

In this Section you will find important information on how to obtain optimum results. You will discover which parameters influence the measurement process and how you can optimize the settings of your instrument to achieve the best measurement results.

#### 15.1.1 Measurement Principle of Halogen Moisture Analyzer

Your instrument performs measurements based on the **thermogravimetric principle**, i.e. the moisture is determined from the weight loss of a sample dried by heating.



In principle, your instrument thus comprises two instruments: An analytical balance and a heating module. In contrast to other thermogravimetric methods (drying oven, infrared, microwave), the Halogen Moisture Analyzer operates with halogen heating technology. This ensures fast heating of the sample and thus guarantees rapid availability of the measurement results.

Irrespective of the measurement method, a correct preparation of the sample and the correct choice of the following measurement parameters improve the quality of the measurement result:

- Sample size
- Drying temperature
- Switch-off mode
- Drying time

#### Attention

Inappropriate setting of these parameters can cause the results to be incorrect or misleading. For this reason, check that the results for each type of sample are what might reasonably be expected.

You will find detailed information on the relationships between these parameters in the delivered application brochure «Guide to Moisture Analysis» or **see Accessories and Spare Parts** (page 105).

In practice not only the quality of the measurement results, but also the speed of the measurement process is important. Thanks to its drying principle (heat generated by a halogen radiator), the Halogen Moisture Analyzer is very fast. You can increase the speed even further through optimum setting of the instrument, e.g. using the **Drying programRapid**.

The optimum drying temperature and the drying time are dependent on the nature and size of the sample and on the desired accuracy of the measurement results. These can be determined only by experiment. The Halogen Moisture Analyzer supports you in this task: It offers result recording of test measurements in the menu **Method Definition**.

#### 15.1.2 Notes on Adjustment of Balance and Heating Module

The balance and the heating module in your drying unit can be adjusted using the appropriate accessories, **see Accessories and Spare Parts** (page 105). The heating module and the balance can also be tested (to check the adjustment). The user can define a test weight or the test temperature, together with permissible tolerances for this test. A test report can be printed out showing the test result has passed or failed.

A Moisture Analyzer is typically used in place of or in addition to the drying oven method. In an oven heat energy is transferred by the flow of air, which establishes an equilibrium between the sample temperature and the ambient temperature. This is not the case in a Moisture Analyzer. The actual sample temperature primarily depends on the specific absorption properties of the sample (dark samples absorb more heat), which can change during the measurement process. There can also be differences between the temperature at the surface of the sample and the temperature inside the sample. The heat output is therefore not dependent on the true sample temperature but instead is regulated by a temperature sensor underneath the halogen heating module.

For the reasons explained above, the sample temperature will be slightly different than the temperature shown on the instrument display. By regularly testing or adjusting the drying unit, you will ensure a consistent and reproducible heat output for the entire lifetime of your instrument.

**Note:**

- METTLER TOLEDO offers an adjustment service – please contact your METTLER TOLEDO representative.
- We recommend to adjust the instrument exclusively under operating conditions.
- After the temperature sensor or the protective glass have been cleaned, we recommend adjusting the heating module using the temperature adjustment kit, **see** Accessories and Spare Parts (page 105). For the procedure for testing or adjusting the drying unit (balance/heating module), **see** Test/Adjust (page 55).

### 15.1.3 Optimum Sample Preparation

Preparation of the sample is decisive for the speed of the measurement process and the quality of the measurement results.

**Note:**

Basic rules for the preparation of your sample:

**The amount of sample you select should be as small as possible and only as large as necessary.**

Excessive amounts of sample require more time for drying and thus prolong the measurement process. If the amount of sample is too small, the measurement result may possibly not be representative of the true moisture content. The following always holds: The greater the inhomogeneity of the sample, the larger the amount of sample needed to obtain a repeatable result .

**Distribute the sample evenly over the sample pan**

You thus increase the surface area of the sample and facilitate heat absorption. The base of the pan should be evenly covered.

With liquid, fat-containing, melting and highly reflecting samples, you should use the sample with the glass fiber filter available as optional equipment, **see** Accessories and Spare Parts (page 105). This also applies to samples which form a skin on their surface when heated. The glass fiber filter ensures even and rapid heat distribution and prevents the formation of a skin on the sample surface.

### 15.1.4 Further Information on Moisture Determination

You will find further information on the moisture determination, the importance of the parameters and the preparation of the samples in the delivered application brochure «Guide to Moisture Analysis» dealing with moisture determination, **see** Accessories and Spare Parts (page 105).

Useful tips and a variety of example methods (comparison between Halogen Moisture Analyzer results and the oven drying method) can be downloaded from:

- ▶ [www.mt.com/moisture](http://www.mt.com/moisture)
- ▶ [www.mt.com/moisture-methods](http://www.mt.com/moisture-methods)
- ▶ [www.moisture-guide.com](http://www.moisture-guide.com)

If you require information on specific applications, your METTLER TOLEDO Customer Service will be pleased to help you.

**Attention**

Moisture determination applications must be optimized and validated by the user according to local regulations. Application-specific data provided by METTLER TOLEDO is intended for guidance only.

## 15.2 Recommended Printer Settings

**English, German, French, Spanish, Italian, Polish, Czech, Hungarian**

<b>Printer</b>			
<b>Model</b>	<b>Char Set</b>	<b>Auto baudrate</b>	<b>Balance feature</b>
<b>RS-P25</b>	IBM/DOS	Off	Disable

<b>Printer</b>				
<b>RS-P42</b>	IBM/DOS <sup>1)</sup>	—	—	—

<b>Instrument / Printer</b>				
<b>Model</b>	<b>Baudrate</b>	<b>Bit / Parity</b>	<b>Stop Bits</b>	<b>Handshake</b>
<b>RS-P25</b>	9600	8/NO	1	Xon/Xoff
<b>RS-P42</b>	1200	8/NO	1	Xon/Xoff

### Brazil Portuguese

<b>Printer</b>				
<b>Model</b>	<b>Char Set</b>	<b>Auto baudrate</b>	<b>Balance feature</b>	
<b>RS-P25</b>	IBM/DOS	Off	Disable	
<b>RS-P42</b>	— <sup>2)</sup>	—	—	

### Instrument / Printer

<b>Model</b>	<b>Baudrate</b>	<b>Bit / Parity</b>	<b>Stop Bits</b>	<b>Handshake</b>
<b>RS-P25</b>	9600	8/NO	1	Xon/Xoff
<b>RS-P42</b>	— <sup>2)</sup>	— <sup>2)</sup>	— <sup>2)</sup>	— <sup>2)</sup>

<sup>1)</sup> Printer settings not available.

<sup>2)</sup> Required font for this language not available.

## 15.3 Installing USB Device Driver

For transmitting MT-SICS commands via USB Device interface, a driver needs to be installed on the connected PC. You can find the USB driver installer for download on the METTLER-TOLEDO website:

► [www.mettler-toledo-support.com](http://www.mettler-toledo-support.com)


### Requirements

- PC with Microsoft Windows® operating system (Windows 32-Bit & 64-Bit: Windows 2000, Windows XP, Windows Vista, Windows 7)
- Internet connection and Web browser (e.g. MS Internet Explorer)
- PC to instrument USB connection cable.

### Installing USB Driver

Navigation: [www.mettler-toledo-support.com](http://www.mettler-toledo-support.com) > login > Customer Support > HS153/HX204 Moisture Analyzers

- 1 Click USB Driver.
- 2 Click USBDriverInstaller.exe.
- 3 Click [Run] to install (recommended) or [Save] to download.
- 4 Click [Run]
- 5 Click [Next] and follow the installer's instructions.



### Installing Instrument

- 1 Switch off moisture analyzer
- 2 Connect the moisture analyzer to the preferred USB Port on the PC.
- 3 Switch the moisture analyzer on.
- 4 Follow the instructions of the wizard and install the software automatically (recommended).



### Note

The wizard appears again for each USB port, either on your PC or if another moisture analyzer is connected.

### Attention

Do not click [Cancel] as for the connected USB port, it might not be possible anymore to perform the installation process.

## 15.4 Third Party License/Notice

This section contains Third Party Software Notices and/or Additional Terms and Conditions for licensed third party software components included within SOFTWARE PRODUCT.

This SOFTWARE PRODUCT is based in part on the work of:

- **Qwt project**  
For user's guide **see** <http://qwt.sf.net>  
For LGPL license V2.1 **see** <http://www.gnu.org/licenses/old-licenses/lgpl-2.1.html>
- **KompexSQLite**  
For GPL license V3 **see** <http://www.gnu.org/licenses/gpl.txt>
- **Qt library 4.8**  
For LGPL license V2.1 **see** <http://qt-project.org/doc/qt-4.7/lgpl.html>  
For GPL license V3 **see** <http://qt-project.org/doc/qt-4.7/gpl.html>
- **decNumber**  
For ICU license V3.68 **see** <http://source.icu-project.org/repos/icu/icu/trunk/license.html>
- **Simpleini**  
For MIT license **see** <http://www.opensource.org/licenses/mit-license.php>

## 16 Index

### A

Access rights	46, 48
Accessories	105
Account	
Policies	49
User	48
Adding comments	83
Adjustment	16, 29
Balance	55
FACT	55
Heating module	55
Notes	109
Printouts	59
Settings	42
Touch screen	38
Weight	56
Weight external	56
Weight internal	56
Anti-theft	11, 28
Appendix	109
Asterisk	72
ATRO	76
Automatic sample chamber	77

### B

Back up	51
Basic elements	17
Battery	96
Brightness	34, 38

### C

Calculated values	72
Chart	85
Chart view	23
Cleaning	90
Color	34, 38
Comments to measurement	83
Commissioning	24
Connecting the Instrument	25
Connectivity	11, 13
Control limits	75
Copy	
Method	65
CSV format	88, 100

### D

Data	100
Data management	50
Date	20, 28, 36
Default settings	37
Define	
Method	65
Shortcut	84
Delete	
see Remove	65
Dimensions	102

Display language	34, 38
Display mode	72
Disposal	94
Draft shield element	11
Drying	
Steps	70
Temperature	67, 68, 68
Unit	11, 26, 99, 100
Unit dimensions	102
Drying program	
Gentle	68
Rapid	67
Standard	66
Dust filter	11, 93

### E

Eco	78
Edit	
Method	65
Shortcut	84
Entering	
Numerical values	19
Text and numbers	18
Error messages	95
Export	
Result	88, 100
Settings and methods	50

### F

FACT	29, 55, 96
Fan	11, 93, 93
Filter	85
Firmware update	52-53
First measurement	30
Fuse	94, 100

### G

General method properties	79
General safety information	8
General settings	16
Gentle drying	68
Graphics panel	22
Graphics view	23, 85
Groups	46

### H

Halogen lamp	11
Heating module	11, 11, 90
History	63
Home screen	14, 16
Host settings	36

### I

Identifications	40
Identifications panel	22
Import	
Settings and methods	50
Inspection window	11

Installation	24	Numerical values	19
Intended Use	8		
Interface	100	<b>O</b>	
Interim results	40	Out of zero range	95
Introduction	7	Overload	95
<b>J</b>			
Journal	85		
<b>K</b>			
Kensington slot	11, 28	Parameter panel	22
Keyboard		Password	35, 48
text and numbers	18	Peripheral settings	36
Keyboard language	34	Power line fuse	11, 94
Keypad		Power supply	11, 100
numerical values	19	Power supply socket	11
Keys on the terminal	14	Preheating	77
<b>L</b>		Printer	
LabX Direct	37	Settings	36, 110
Languages	34, 38	Printout	
Printout	40	Intermediate results	40
Level		Language	40
Indicator	11	Short	87
Sensor	11, 28, 96	Standard	87
Leveling	27	Protective clothing	9
Leveling screw	11		
Limits	75	<b>R</b>	
Lists	21	Ramp time	69
Location	24	Rapid drying	67
Login	49	Reading angle	28
<b>M</b>		Remove	
Maintenance		Method	65
Cleaning	90	Shortcut	84
Dust filter	93	Replace	
Heating module	90	Dust filter	93
Power line fuse	94	Power line fuse	94
Measurement	16	Reset	52
First	30	Resolution	76
Measurement principle	109	Restore	51
Memory Card	13	Result	
Memory stick	13, 50	Export	88, 100
Method		Result and value handling	75
Copy	65	Results	16, 85, 85
Definition	64	RS232C	12, 13
Edit	16, 65		
Export and import	50	<b>S</b>	
Name	22, 79, 79	Safety Information	
New	16, 65	Intended use	8
Properties	79	Protective clothing	9
Remove	65	Signal words	8
Renaming	79	Staff safety	9
Test	80	Warning Symbols	8
MT-SICS	36	Safety information	
<b>N</b>		General	8
New method	65	Sample chamber	11, 14
Numbers	18	Sample pan handler	11
		Sample pan holder	11
		Sample preparation	110
		Scope of delivery	24
		Screen settings	34, 38, 38
		SD card	13
		Selecting the location	24

Setting up drying unit	26	Test	16
Settings	16	Balance	60
Adjustment	42	Heating device	60
Date	20, 28, 36	Measurement	80, 88
Export and import	50	Method	80, 88
Host	36	Temperature	61
Peripheral	36	Time	80
Regional	36	Weight external	60
Screen	34	Weight internal	60
System	36	Text	18
Temperature Test	43	Thermogravimetric	109
Time	20, 28, 36	Time	20, 28, 36
Weight adjustment	44	Touch screen	14
Weight test	43	Touch screen adjustment	38
Shortcuts	16, 17, 22, 83	Troubleshooting	95
Define	84		
Edit	84		
Remove	84		
Show results	16	Underload	95
Signal words	8	Unpacking	24
SOC	70	Update	53
Software update	52-53	USB	12
Sound	34	USB Device	13
Spare parts	105	USB Driver	
Staff Safety	9	Installation	111
Stand for terminal	27	USB Host	13
Standard drying	66	USB Memory stick	
Standard equipment	24	see memory stick	50
Standby	14, 78	User	
Start measurement	16	Account	48
Start weight	74, 83	Groups	46
Starting mode	77	Home screen	16
Startup user	49	Interface	15
Status icon	96	Management	46
Status messages	17, 95	Profile see User management	46
Stop drying	83, 88	Shortcuts	16, 83
Switch button	19		
Switch ON/OFF	14		
Switch-off criterion	70, 80, 88	Value panel	22
Switch-off time	78		
System	11, 13		
System management	50	W	
System settings	36	Warning Symbols	8
		Weighing-in aid	74, 83
		Weight	
		Adjustment external	56
		Adjustment internal	56
		Test external	60
		Test internal	60
		Weight adjustment	
		Settings	44
		Weight test	
		Settings	43
		Work screen	22
		Workflow handling	77
T			
Tables	21		
Technical data	99		
Temperatur			
Adjustment settings	44		
Temperature			
Adjustment kit	11		
Sensor	11		
Standby	78		
Switch-off criterion	70		
Test	61		
Test settings	43		
Terminal	28, 90		
Terminal dimensions	103		



## **GWP® – Good Weighing Practice™**

The global weighing guideline GWP® reduces risks associated with your weighing processes and helps to

- choose the appropriate balance
- reduce costs by optimizing testing procedures
- comply with the most common regulatory requirements

► **[www.mt.com/GWP](http://www.mt.com/GWP)**

**[www.mt.com/hxhs](http://www.mt.com/hxhs)**

For more information

### **Mettler-Toledo AG, Laboratory & Weighing Technologies**

CH-8606 Greifensee, Switzerland

Tel. +41 (0)44 944 22 11

Fax +41 (0)44 944 30 60

[www.mt.com](http://www.mt.com)

Subject to technical changes.

© Mettler-Toledo AG 12/2012

30019565A en



\* 3 0 0 1 9 5 6 5 \*